INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

# Serial No.: OR / KDA / BSR – 276

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	<ul> <li>Siva-Kali Temple (Temple No -68), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda</li> <li></li> <li>I</li> </ul>
<b>LONGITUDE</b> 85°50'05" E	LATITUDE 20°14'26" N ELEVATION 70 ft
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple, on the west of Grand Lingaraja and north of Rama-Sita temple within the complex is situated in Old Town, Bhubaneswar.
3. Property Type	
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures       Other Structures            ✓ Temple        Wall          Mosque       Gateway         Minar       Pillar         Church       Others (specify)         Monastery       Stupa         Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote.Public square Park or garden Graveyard Baolis, Well Tank CaveThe temple has a rekha vimana of Kalingan order.

		ABANDONED / IN USE : In use
Present	:	Living temple, the enshrining deity is a Sivalinga withi
		a yonipitha.
Past		Worshipped
5. Age (Source)		
PERIOD	•	Somavamsi rule
YEARS		14 <sup>th</sup> century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	The temple is repaired and conserved b
		Archeological Survey of India.
Destruction / Demolition	:	
6. Ownership / Level of Protection	n	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of	:	Protected monument of Archaeological survey of India
India / State Archaeology		<b>C</b> .
Department / Any Other (Please		
specify)		
Private		Lingaraja Temple Trust Board maintains the rituals
		the temple
Any other (Please specify)		Endowment Department, Government of Oriss manages the property of the temple.
Name		הומהמעכי נווב אוסטבונע טו נווב נכוווטוב.
Address	:	Archaeological Survey of India, Bhubaneswar Circle
		153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone		0674- 2558170
7. Association		
WITH EVENTS		
In History		
	:	 Sivaratir, Sankranti, Kartikapurnima, etc are observe
In Rituals		 <i>Sivaratir, Sankranti, Kartikapurnima,</i> etc are observe here.
In Rituals		
In Rituals	:	
In Rituals	:	here.
In Rituals In Building Construction Any other (specify) • WITH PERSONS	::	here.  Thread ceremony Archaeological Survey of India and Endowme
In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron	::	here.  Thread ceremony
In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer	::	here.  Thread ceremony Archaeological Survey of India and Endowme Department, Government of Orissa 
In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer	::	here.  Thread ceremony Archaeological Survey of India and Endowme
In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify)	::	here.  Thread ceremony Archaeological Survey of India and Endowmer Department, Government of Orissa 
In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron	:	here.  Thread ceremony Archaeological Survey of India and Endowme Department, Government of Orissa 
In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	:	here.  Thread ceremony Archaeological Survey of India and Endowme Department, Government of Orissa  Lingaraja Temple Trust Board
In Rituals In Building Construction Any other (specify)  • WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological Historical	: : : :	here.  Thread ceremony Archaeological Survey of India and Endowme Department, Government of Orissa  Lingaraja Temple Trust Board
In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological	: : : ·	 Thread ceremony Archaeological Survey of India and Endowmen Department, Government of Orissa  Lingaraja Temple Trust Board

*parsvadevata* images, the temple can be dated to the 14<sup>th</sup> century A.D. i.e. the Ganga rule in Orissa.

# **SECTION II: DESCRIPTION**

# 9. Physical Description and Decorative Features

<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings (</b> Attach extra sheet if necessary) No : Urban setting
Gunounungo	Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :
• <b>Quantification</b> Area Dimension (L x B x H)	: 5.50 mtrs x 4.65 mtrs x 8.50 mtrs (approximate height)
Number of Blocks Number of Storys	( <b>m</b> / cm/ feet / inch) : N.A.
• <b>Spatial Organization</b> Orientation Plan Allocation of Spaces	<ul> <li>Facing towards east.</li> <li>The <i>vimana</i> is square on plan.</li> <li>158.49 mtrs x 141.73 mtrs in length and breadth respectively.</li> </ul>
ARCHITECTURAL STYLE <ul> <li>Ornamentation</li> <li>Exteriors</li> </ul>	: Decorated with three miniature <i>rekha</i> temples surmounted by an <i>udyotasimha</i> over the <i>kirtimukha</i> pedestal on the each <i>raha</i> and a miniature <i>rekha</i> <i>mundi</i> on the <i>anuratha paga</i> just above the <i>varanda</i> . The <i>parsvadevata</i> images are Ganesa, Kartikeya and
Interiors Movable Collections * <b>Any Other</b> (specify)	<ul> <li>Parvati on the southern, western and northern side respectively.</li> <li>Plain</li> <li>Nil</li> <li>The temple is <i>pancharatha</i> on plan and <i>panchanga bada</i> in elevation.</li> </ul>
10. Construction Technology	
Structural System Building Techniques Material of Construction	<ul> <li><i>Rekha vimana</i> of <i>Kalingan</i> order.</li> <li>Ashlar dry masonry</li> <li>Sandstone is used for the construction of the temple and black chlorite for the <i>parsvadevata</i> images.</li> </ul>
11. Condition Assessment	
In General	Good / Fair : Good
	Sign of Deterioration

Se
Da

rious Deterioration inger of Disappearance

### In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation.

#### 12. Threats to the Property

Γ	✓	Natural
		Negligence
		Vandalism
	$\checkmark$	Urban Pressures

# **SECTION III: REFERENCES**

#### 13. Reference Sources (published and unpublished textual details)

- 1. K. S. Behera, 2008, The Lingaraja Temple of Bhubaneswar, Art and Cultural Legacy, New Delhi.
- Debala Mitra, 1961, Bhubaneswar, ASI, New Delhi. 2.

#### 14. Photographs: 25 nos (attach list as in page 6, in case of multiple photographs) Photo Reference 1 CAPTION : 15. Audio / Video (related to rituals / performance / festivals etc.) Reference : : DESCRIPTION 16. Maps/Plans/Drawings 17. Listers NAME : Jaya Shankar Naik NAME : 18. Reviewers Dr. S. Pradhan NAME : NAME : COMMENTS COMMENTS :