INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR – 279

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	 Siva Temple (Temple No 125), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
LONGITUDE 85°50'05" E Address	LATITUDE 20 ⁰ 14 ² 26 [°] N ELEVATION 70 ft. : Village (village code) Lingaraja Temple Complex
Approach 3. Property Type	 Post : Old Town Tehsil: Bhubaneswar State : Orissa The temple, on the east of the Grand Lingaraja within the complex and close to the eastern enclosure wall is situated in Old Town, Bhubaneswar.
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures Other Structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote.Public square Park or gardenThe temple has a rekha vimana of Kalingan order.Graveyard Baolis, Well Tank CaveCave

		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a Sivalinga within a circular <i>yonipitha</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	Suryavamsi Gajapati rule
YEARS	:	16 th century AD.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	The temple was renovated and conserved by
Destruction / Demolition	:	Archaeological Survey of India.
6. Ownership / Level of Protection	n	
Dublic Archeological Oracle	_	SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Archaeological Survey of India
Private	:	Lingaraja Temple Trust Board maintains the rituals of
	•	the temple.
Any other (Please specify)	:	Endowment Department, Government of Oriss
		manages the property of the temple.
Name	:	
Address	:	Archaeological Survey of India, Bhubaneswar Circle
Phone		153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. 0674- 2558170
7. Association	•	0074-2330170
WITH EVENTS		
In History In Rituals	•	 Sivaratri, Kartika Purnima, Sankranti, etc.
In Building Construction	:	
Any other (specify)	÷	Thread ceremony, engagements etc are held here.
WITH PERSONS	-	
Patron	:	Archeological Survey of India and Endowmer Department, Government of Orissa.
Architect / Engineer	:	
Any other (specify)	:	Lingaraja Temple Trust Board
8. Statement of Significance		
Architectural	✓	Architectural
Archaeological		
Archaeological Historical		
	✓	Religious

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Urban setting	
Surroundings		Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :	
• Quantification Area Dimension (L x B x H)	:	1.65 mtrs x 1.55 mtrs x 3.50 mtrs (approximate height) (m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	One N.A.	
• Spatial Organization Orientation Plan Allocation of Spaces	:	Facing towards north. The <i>vimana</i> is square on plan. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.	
ARCHITECTURAL STYLE Ornamentation			
Exteriors	:	Devoid of any decoration except a <i>khakharamundi</i> up to its <i>gandi</i> portion is designed in the <i>talagarbhika</i> and the <i>mastaka</i> of the same is formed in the <i>urdhagarbhika</i> . The frontal <i>raha</i> has an uncarved <i>chaitya</i> motif surmounted by a female figure.	
Interiors	:	Plain	
Movable Collections * Any Other (specify)	:	Nil The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.	
10. Construction Technology			
Structural System	:	The <i>vimana</i> of the temple is <i>rekha</i> order of <i>Kalingan</i> style.	
Building Techniques	:	Ashlar dry masonry	

Building Techniques Material of Construction	:	Ashlar dry masonry Sandstone is used for the construction of the temple.
---	---	---

11. Condition Assessment

In General						

Good / Fair : Good Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation due to renovation work.

12. Threats to the Property

✓	Natural
	Negligence
	Vandalism
✓	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar*, *Art and Cultural Legacy*, New Delhi.
- 2. Debala Mitra, 1961, *Bhubaneswar*, ASI, New Delhi.
- 3.

14. Photographs: 06 nos

			(attach list as in page 6, in case of multiple photographs)
Photo Referen CAPTION	се	:	
15. Audio / Vi	deo		
			(related to rituals / performance / festivals etc.)
Reference DESCRIPTIO	N	:	
16. Maps/Plar	ns/Drawings		
17. Listers			
NAME :	Jaya Shankar Naik		NAME :
18. Reviewers	5		
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMMENTS :