INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR – 281

	SECTION I : IDENTIFICATION
1. Name	
Present	 Siva Temple Near Ekambaresvara Temple (Temple No100), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
Past Other Name (if any):	: :
2. Location	
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ² 26 [°] N ELEVATION 70 ft.
Address	 Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple, on the north of the Grand Lingaraja and near Ekambaresvara temple within the complex is situated in Old Town, Bhubaneswar.
3. Property Type	
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Other Structures Image: Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote.Public squareThe temple has a rekha vimana of Kalingan order.Park or gardenVimana of Kalingan order.GraveyardBaolis, WellTankCave

		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a Sivalinga within a square <i>yonipitha</i> , made of black chlorite.
Past	:	Worshipped
5. Age (Source)		
PERIOD		Late Ganga rule
YEARS	:	14 th century AD.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	The temple is completely renovated and conserved by
Subsequent changes	•	Archaeological Survey of India.
Destruction / Demolition	:	
6. Ownership / Level of Protectic	h	
o. Ownership / Lever of Frotectio	<u>///</u>	SINGLE /MULTIPLE : Multiple
Dublic : Archaeological Survey of		•
Public : Archaeological Survey of India / State Archaeology	•	Protected monument of Archaeological Survey of India
India / State Archaeology Department / Any Other (Please		
specify)		
Private		Lingaraja Temple Trust Board maintains the rituals o
Flivale	•	• •
Any other (Please specify)		the temple. Endowment Department, Government of Orissa
Any other (Flease specify)	•	manages the property of the temple.
Name		
Address	:	Archaeological Survey of India, Bhubaneswar Circle
Address	•	153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone	:	0674- 2558170
7. Association		
WITH EVENTS		
• WITH EVENTS In History	:	
In History	:	 Sivaratri, Kartika Purnima. Sankranti. etc.
In History In Rituals	:	 Sivaratri, Kartika Purnima, Sankranti, etc.
In History In Rituals In Building Construction	: : :	 Sivaratri, Kartika Purnima, Sankranti, etc.
In History In Rituals In Building Construction	: :	 Sivaratri, Kartika Purnima, Sankranti, etc.
In History In Rituals In Building Construction Any other (specify)		
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS		 Archeological Survey of India and Endowmen
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron		
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer		 Archeological Survey of India and Endowmen
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify)		 Archeological Survey of India and Endowmen Department, Government of Orissa.
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron	· · · · · · · · · · · · · · · · · · ·	 Archeological Survey of India and Endowmen Department, Government of Orissa. Lingaraja Temple Trust Board
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural	· · · · · · · · · · · · · · · · · · ·	 Archeological Survey of India and Endowmen Department, Government of Orissa.
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	: : : :	 Archeological Survey of India and Endowmen Department, Government of Orissa. Lingaraja Temple Trust Board
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological Historical	: : : : : : · · · · · · · · · · · · · ·	 Archeological Survey of India and Endowmen Department, Government of Orissa. Lingaraja Temple Trust Board
In History In Rituals In Building Construction Any other (specify) • WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological	······································	 Archeological Survey of India and Endowment Department, Government of Orissa. Lingaraja Temple Trust Board Architectural

SECTION II: DESCRIPTION

 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) : No : Urban setting
ounounungo	Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :
Quantification	
Area Dimension (L x B x H)	: 4.20 mtrs x 2.80 mtrs x 5.50 mtrs (approximate height) (m / cm/ feet / inch
Number of Blocks	: One
Number of Storys	: N.A.
Spatial Organization	
Orientation	: Facing towards west.
Plan	: The vimana is square on plan that stands over a pista
	of 0.30 mtrs in height.
Allocation of Spaces	: 158.49 mtrs x 141.73 mtrs in length and breadth
	respectively.
ARCHITECTURAL STYLE	
 Ornamentation 	
Exteriors	: Devoid of any decoration except a miniature angasikhara surmounted by a gajakranta motif on the frontal raha and the doorjambs have pidhamundi at the base, Gaja-Laxmi in the lintel and navagraha panel in the architrave.
Interiors	: Plain
Movable Collections	: Nil
* Any Other (specify)	: The temple is <i>pancharatha</i> on plan and panchangabada in elevation.
10. Construction Technology	
Structural System Building Techniques Material of Construction	 <i>Rekha vimana</i> of <i>Kalingan</i> order. Ashlar dry masonry Sandstone is used for the construction of the temple and the <i>pista</i>.
11. Condition Assessment	
In General Good / Fa	air : Good
Sign c	of Deterioration
	us Deterioration
	er of Disappearance

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation due to recent renovation work.

12. Threats to the Property

✓	Natural
	Negligence
	Vandalism
✓	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar*, *Art and Cultural Legacy*, New Delhi.
- 2. Debala Mitra, 1961, *Bhubaneswar*, ASI, New Delhi.
- 3.

14. Photographs: 07 nos

			(attach list as in page 6, in case of multiple photographs)			
Photo Referen CAPTION	се	:				
15. Audio / Vi	deo					
			(related to rituals / performance / festivals etc.)			
Reference DESCRIPTION	٨	:				
16. Maps/Plans/Drawings						
17. Listers						
NAME :	Jaya Shankar Naik		NAME :			
18. Reviewers						
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMMENTS :			