

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 282

	SECTION I: IDENTIFICATION
1. Name	
Present	: Siva Temple North of Parvati Temple (Temple No77), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
Past Other Name (if any):	: :
2. Location	
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ['] 26 ["] N ELEVATION 70 ft.
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple, on the north of the Grand Lingaraja and north of Parvati temple within the complex is situated in Old Town, Bhubaneswar.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a rekha vimana of Kalingan order.

4. Property Use

ABANDONED / IN USE: In use

Present : Living temple, the presiding deity is a Sivalinga within

a circular yonipitha.

Past : Worshipped

5. Age (Source)

PERIOD : Suryavamsi Gajapati rule

YEARS: 16th century AD.

Precise date of Construction : --Completion : ---

Subsequent changes : The temple was renovated and conserved by

Archaeological Survey of India.

Destruction / Demolition : Presently the crowning element of the temple is

missing.

6. Ownership / Level of Protection

SINGLE / MULTIPLE : Multiple

Protected monument of Archaeological Survey of India

Public: Archaeological Survey of:
India / State Archaeology
Department / Any Other (Please

specify)

Private : Lingaraja Temple Trust Board maintains the rituals of

the temple.

Any other (Please specify) : Endowment Department, Government of Orissa

manages the property of the temple.

Name : ---

Address : Archaeological Survey of India, Bhubaneswar Circle,

153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.

Phone : 0674- 2558170

7. Association

WITH EVENTS

In History : --

In Rituals : Sivaratri, Kartika Purnima, Sankranti, etc.

In Building Construction : --Any other (specify) : ---

• WITH PERSONS

Patron : Archeological Survey of India and Endowment

Department, Government of Orissa.

Architect / Engineer : ----

Any other (specify) : Lingaraja Temple Trust Board

8. Statement of Significance

Architectural ✓ Architectural Archaeological

Historical

Religious \(\sqrt{Religious} \)

Any other(spedify) : On architectural ground, the temple can be dated to the late

Suryavamsi Gajapati rule.

SECTION II: DESCRIPTION

9. Physical Description and Deco	rati	ive Features
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Urban setting
		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
Quantification		
Area Dimension (L x B x H)	:	2.86 mtrs x 2.50 mtrs x 4.00 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks	:	One
Number of Storys	:	N.A.
04:-1 0:4:		
 Spatial Organization Orientation 		Facing towards east.
Plan	:	The <i>vimana</i> is square on plan that stands over a <i>pista</i>
		of 0.24 mtrs in height.
Allocation of Spaces	:	158.49 mtrs x 141.73 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE		
Ornamentation		
Exteriors	:	Devoid of any decoration except a <i>khakharamundi</i> on the frontal <i>raha</i> and remains of <i>navagraha</i> panel in the architrave.
Interiors	:	Plain
Movable Collections	:	Nil
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction	:	Rekha vimana of Kalingan order. Ashlar dry masonry Laterite is used for the construction of the temple and the pista whereas Sandstone for the doorjambs and the navagraha panel.
11. Condition Assessment		
In General Good / Fair Sign of De Serious D Danger of	ete	
In Brief (Attach extra cheet if need	^^	anu).

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation due to recent renovation work.

12. Threats to the Property	<u></u>
	✓ Natural
	Negligence
-	✓ Vandalism
L	✓ Urban Pressures
SEC	CTION III: REFERENCES
13. Reference Sources (published	and unpublished textual details)
1. K. S. Behera, 2008, <i>The Lingar</i> Delhi.	raja Temple of Bhubaneswar, Art and Cultural Legacy, New
 Debala Mitra, 1961, Bhubanes . 	war, ASI, New Delhi.
14. Photographs: 10 nos	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	:
CAPTION	:
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	:
16. Maps/Plans/Drawings	
17. Listers	
NAME: Jaya Shankar Naik	NAME :
18. Reviewers	
NAME: Dr. S. Pradhan	NAME :