

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 283

	SECTION I: IDENTIFICATION			
1. Name				
Present	: Siva Temple South of Natamandapa (Temple No 19), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda			
Past Other Name (if any):	: :			
2. Location				
LONGITUDE 85°50′05″ E	LATITUDE 20 ⁰ 14 ² 26 ⁸ N ELEVATION 70 ft.			
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002			
Approach	: The temple is situated at a distance of 3.00 mtrs south of the Grand Lingaraja within the complex in Old Town, Bhubaneswar.			
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify) Others (specify)			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a rekha vimana of Kalingan order.			

4. Property Use ABANDONED / IN USE: In use Living temple, the presiding deity is a Sivalinga within Present a circular yonipitha. Worshipped **Past** 5. Age (Source) **PERIOD** Suryavamsi Gajapati rule **YEARS** 16th century AD. **Precise date of Construction** Completion Subsequent changes The upper portion of the *gandi* is completely renovated by Archaeological Survey of India. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple Protected monument of Archaeological Survey of India **Public**: Archaeological Survey of : State Archaeology / Department / Any Other (Please specify) **Private** Lingaraja Temple Trust Board maintains the rituals of the temple. Any other (Please specify) Endowment Department, Government of Orissa manages the property of the temple. Name Address Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. **Phone** 0674-2558170 7. Association WITH EVENTS In History In Rituals Sivaratri, Kartika Purnima, etc observed here. In Building Construction : Any other (specify) Thread ceremony, engagements, etc held here. WITH PERSONS Patron Archeological Survey of India and Endowment

Department, Government of Orissa.

Architect / Engineer

Any other (specify) Lingaraja Temple Trust Board

8 Statement of Significance

0. 3	tatement of Significance		
	Architectural	✓	Architectural
1	Archaeological		
H	Historical		
F	Religious	\checkmark	Religious
	Any other (specify)	:	On architectural ground and iconographical feature of

the parsvadevata images, the temple can be assigned

to the Suryavamsi Gajapati rule.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features					
 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) : No Urban setting			
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex		
 Quantification Area Dimension (L x B x H) 	:	2.90 mtrs x 2.90 mtrs x 5.00 mtrs	(m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	One N.A.			
 Spatial Organization Orientation Plan Allocation of Spaces 	: :	Facing towards east. Consists of a square <i>vimana</i> . 158.49 mtrs x 141.73 mtrs in length and breadth respectively.			
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections * Any Other (specify) 10. Construction Technology	: : : : : :	Devoid of any decorations except the frontal <i>raha</i> . Plain Nil The temple is <i>pancharatha</i> <i>panchangabada</i> in elevation.			
Structural System Building Techniques Material of Construction 11. Condition Assessment	:	Rekha vimana of Kalingan order. Ashlar dry masonry Laterite is used up to the half of the is in Sandstone. Traces of lime the exterior surface of the temple.			
In General Good / Fair	r :	Fair			
✓ Sign of Serious	Dete Dete	rioration erioration isappearance			
In Brief (Attach extra sheet if no	eces	sary):			

Minor cracks are noticed in the *bada* of the temple.

12. Threats to the Property
✓ Natural Negligence Vandalism ✓ Urban Pressures x x x x x x x x x x x x x x x x x x x
SECTION III: REFERENCES
13. Reference Sources (published and unpublished textual details)
 K. S. Behera, 2008, <i>The Lingaraja Temple of Bhubaneswar</i>, <i>Art and Cultural Legacy</i>, New Delhi. Debala Mitra, 1961, <i>Bhubaneswar</i>, ASI, New Delhi. 4.
14. Photographs: 06 nos
(attach list as in page 6, in case of multiple photographs Photo Reference : CAPTION : 15. Audio / Video
(related to rituals / performance / festivals etc
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers
NAME : Jaya Shankar Naik NAME :
18. Reviewers
NAME : Dr. S. Pradhan NAME : COMMENTS :