

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 285 **SECTION I: IDENTIFICATION** 1. Name Present Temple No - 63, Lingaraja Temple Complex, Bhubaneswar, Dist. - Khurda Past Other Name (if any): 2. Location **LONGITUDE** 85⁰50'05" E 20⁰14²6⁸ N LATITUDE **ELEVATION** 70 ft **Address** Village (village code) Lingaraja Temple Complex Post: Old Town Via: Old Town, Bhubaneswar Tehsil: Bhubaneswar District: Khurda State: Orissa **PIN**: 751002 **Approach** The temple, on the west of Grand Lingaraja and close to the western enclosure wall within the complex is situated in Old Town, Bhubaneswar. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note. structures The temple has a rekha Public square Bridge vimana of Kalingan order. It is Tunnel Park or garden a non-living temple and its Other engineering structure Graveyard religious affiliations are not Baolis, Well Tank clear, as sanctum and the parsvadevata Cave niches are

empty. However, according to local traditions, it was a vaisnava temple which enjoyed worship for a considerable period of time.

4. Property Use

ABANDONED / IN USE: Abandoned

Present Non-living temple and the presiding deity is missing

now.

Past Worshipped.

5. Age (Source)

PERIOD Ganga rule 13th century AD YEARS

First half of the 13th century AD Precise date of Construction

Completion

Subsequent changes Renovated and conserved by Archaeological Survey of

India.

Destruction / Demolition Now the facing stones of the platform are not intact.

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple

Public: Archaeological Survey of : Protected monument of Archaeological Survey of India.

Archaeology State /

Department / Any Other (Please

specify)

Private Lingaraja Temple Trust Board maintains the rituals of

the temple.

Any other (Please specify) Endowment Department, Government of Orissa

manages the property of the temple.

Name

Archaeological Survey of India, Bhubaneswar Circle, Address

153-VIP Area, Nayapalli, Bhubaneswar, Orissa.

0674-2558170 **Phone**

7. Association

• WITH EVENTS

NA In History In Rituals NA In Building Construction NA Any other (specify) NA

WITH PERSONS

Patron Archeological Survey of India and Endowment

Department, Government of Orissa.

Architect / Engineer

Any other (specify) Lingaraja Temple Trust Board

8. Statement of Significance

Architectural Architectural

Archaeological					
Historical					
Religious					
Any other (specify)	:	On	the	basis	of

the architectural features and rich decorative programmed, the temple can be assigned to the first half of 12th century AD. i.e. the Ganga rule of

Orissa.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context

Urban / Rural Setting

Surroundings

* **Drawings (**Attach extra sheet if necessary) Nο

Urban setting

Stand in Isolation Integral part of a Landscape

/ Street / Complex :

Quantification

Area Dimension (LxBxH) 5.80 mtrs x 5.60 mtrs x 11.00 mtrs (approximate

height)

(m / cm/ feet / inch)

Complex

Number of Blocks One Number of Storys N.A.

Spatial Organization

Orientation Facing towards east.

Plan A square vimana that stands over an ornamented pista

of 0.90 mtrs in height.

Allocation of Spaces 158.49 mtrs x 141.73 mtrs in length and breadth

respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors Decorated with architectural motifs like

> khakharamundis and pidhamundis in the lower and upper jangha respectively in the kanika and anuraha pagas; four anga-sikharas diminishing in size successively in the anuraha pagas; elongated khakharamundi with flanking pilaster in talagarbhika; a miniature rekhamundi surmounted by a gaja-kranta motif on the frontal raha; decorative motifs like-gaja-vidala and navikas in the recess of the pagas. scroll works, major vajramastaka mounted by a gajakranta in the raha except the eastern one, dopichhasimhas and figures of Garuda placed on the beki to support the amala, semi-divine figures like-dikpalas and their consorts; secular images like - nayikas in

different mood etc.

Plain Interiors Movable Collections Nil

* Any Other (specify)	: The temple is saptaratha on plan and panchangabada in elevation.		
10. Construction Technology			
Structural System Building Techniques Material of Construction	 Rekha vimana of Kalingan order. Ashlar dry masonry Sandstone is used for the construction of the temple. 		
11. Condition Assessment			
In General Good / Fair ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance	: Fair		
In Brief (Attach extra sheet if nec	essary):		
Most of the images in the pista are	eroded and weathered.		
12. Threats to the Property			
× × × × × × × × × × × × × × × × × × ×	✓ Natural Negligence Vandalism ✓ Urban Pressures		
<u>SE</u>	ECTION III: REFERENCES		
13. Reference Sources (published	l and unpublished textual details)		
 K. S. Behera, 2008, The Lingaraja Temple of Bhubaneswar, Art and Cultural Legacy, New Delhi. Debala Mitra, 1961, Bhubaneswar, ASI, New Delhi. 			
14. Photographs: 11 nos			
	(attach list as in page 6, in case of multiple photographs)		
Photo Reference CAPTION 15. Audio / Video	: :		
	(related to rituals / performance / festivals etc.)		
Reference DESCRIPTION	: :		
16. Maps/Plans/Drawings			
17. Listers			
NAME: Jaya Shankar Naik	NAME:		

18. Reviewers

NAME : Dr. S. Pradhan COMMENTS

NAME : COMMENTS :