INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR – 289

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any): 2. Location	 Unidentified Siva Temple (Temple No 86), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
21 20041011	
LONGITUDE 85 ⁰ 50 [°] 05 [°] E	LATITUDE 20 ⁰ 14 ² 26 [°] N ELEVATION 70 ft.
Address	 Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple is situated on the north of the Grand Lingaraja within the complex in Old Town, Bhubaneswar.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Other Structures ✓ Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote.Public squareThe temple has a rekha vimana of Kalingan order.Park or gardenVimana of Kalingan order.GraveyardBaolis, WellTankCave

		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a Sivalinga upon a circular <i>yonipitha</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	Suryavamsi Gajapati rule
YEARS	÷	16 th century AD
Precise date of Construction	:	Second half of the 16 th century AD.
Completion	:	
Subsequent changes	:	Renovated and conserved by Archaeological Survey of
		India.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey ofIndia/StateArchaeologyDepartment/AnyOtherOther(Please)	:	Protected monument of Archaeological Survey of India
specify)		
Private	:	Lingaraja Temple Trust Board maintains the rituals of the temple.
Any other (Please specify)	:	Endowment Department, Government of Orissa manages the property of the temple.
Name	:	
Address	:	Archaeological Survey of India, Bhubaneswar Circle 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone	:	0674- 2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Kartika Purnima, Sankranti, etc performed
In Building Construction		here.
Any other (specify)	:	Thread ceremony, engagements, etc held here.
WITH PERSONS	•	misaa ooromony, ongagomento, ete neta nere.
Patron	:	Archeological Survey of India and Endowmen Department, Government of Orissa.
Architect / Engineer	:	
Any other (specify)	;	Lingaraja Temple Trust Board
8. Statement of Significance	•	
• • • • •	✓	Architectural
Architectural	•	
Architectural Archaeological	•	
	·	
Archaeological	✓	Religious

On architectural ground, the temple can be assigned to the late Gajapati rule i.e. about the second half of the 16th century AD. SECTION II: DESCRIPTION 9. Physical Description and Decorative Features * Drawings (Attach extra sheet if necessary) : No Context Urban / Rural Setting : Urban setting Surroundings Stand in Isolation Complex Integral part of a Landscape / Street / Complex : Quantification Area Dimension (L x B x H) : 3.15 mtrs x 2.65 mtrs x 6.00 mtrs (approximate height) $(\mathbf{m} / \mathbf{cm} / \mathbf{feet} / \mathbf{inch})$ Number of Blocks : One Number of Storys N.A. **Spatial Organization** Orientation Facing towards east. Plan A square vimana that stands over a platform of 0.40 : mtrs in height. Allocation of Spaces 158.49 mtrs x 141.73 mtrs in length and breadth respectively. ARCHITECTURAL STYLE Ornamentation Exteriors Devoid of any decoration except the *navagraha* panel in the architrave and Gaja-Laxmi in the lintel. Interiors Plain Movable Collections Nil : * Any Other (specify) The temple is *pancharatha* on plan and *triangabada* in elevation. **10. Construction Technology** Structural System : Rekha vimana of Kalingan order. **Building Techniques** Ashlar dry masonry Material of Construction Laterite is used for the construction of the temple and Sandstone for the *pista* and the doorjambs. **11. Condition Assessment** In General Good / Fair : Fair Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Due to the ravages of nature the exterior surface of the temple is eroded and weathered.

12. Threats to the Property

\checkmark	Natural
	Negligence
	Vandalism
\checkmark	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar*, *Art and Cultural Legacy*, New Delhi.
- 2. Debala Mitra, 1961, *Bhubaneswar*, ASI, New Delhi.
- 3.

14. Photographs: 05 nos

		(attach list as in page 6, in case of multiple photographs)
Photo Referen CAPTION	ce :	
15. Audio / Vie	deo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	: I :	
16. Maps/Plan	s/Drawings	
17. Listers		
NAME :	Jaya Shankar Naik	NAME :

18. Reviewers

NAME : Dr. S. Pradhan COMMENTS NAME : COMMENTS :