

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 290

1. Name	SECTION I: IDENTIFICATION
Present Past Other Name (if any): 2. Location	 Unidentified Siva Temple (Temple No 96), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
LONGITUDE 85°50'05" E	LATITUDE 20°14'26" N ELEVATION 70 ft.
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple, on the north of the Grand Lingaraja within the complex is situated in Old Town, Bhubaneswar
3. Property Type	
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a rekha vimana of Kalingan order.

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the presiding deity is a Sivalinga within
Past	:	a circular <i>yonipitha</i> . Worshipped
5. Age (Source)		
		_
PERIOD	:	Ganga rule
YEARS Precise date of Construction	•	14 th century AD.
Completion	:	
Subsequent changes	:	Renovated and conserved by Archaeological Survey of India.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology	:	Protected monument of Archaeological Survey of India
Department / Any Other (Please		
specify)		
Private	:	Lingaraja Temple Trust Board maintains the rituals of the temple.
Any other (Please specify)	:	Endowment Department, Government of Orissa manages the property of the temple.
Name	:	
Address	:	Archaeological Survey of India, Bhubaneswar Circle,
Phone	:	153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. 0674- 2558170
7. Association		
WITH EVENTS In History		
In Rituals	:	Sivaratri, Ekadasi, Kartika Purnima, etc held here.
In Building Construction	:	
Any other (specify)	:	Thread ceremony, engagements, etc held here.
WITH PERSONS Betree		Archeological Survey of India and Endowment
Patron	•	Archeological Survey of India and Endowment Department, Government of Orissa.
Architect / Engineer	:	Linguagia Taganla Tayat Dagad
Any other (specify)	:	Lingaraja Temple Trust Board
8. Statement of Significance		
Architectural Archaeological	✓	Architectural
Historical		D. K. C
Religious	√	Religious
Any other (specify)		

On architectural ground and iconographical feature of the *parsvadevata* images, the temple can be dated to the late Ganga rule.

SECTION II: DESCRIPTION

<u>9</u>	LUI	HOW II. DECOMIT HOW
9. Physical Description and Dec	orat	ive Features
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary): No Urban setting
Surroundings		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
 Quantification Area Dimension (L x B x H) 	:	4.75 mtrs x 4.00 mtrs x 8.50 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks Number of Storys	:	One N.A.
 Spatial Organization Orientation Plan Allocation of Spaces 	: :	Facing towards east. A square <i>vimana</i> that stands over a platform of 0.40 mtrs in height. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	Decorated with a <i>khakharamundi</i> in the centre flanked by two miniature <i>rekhamundis</i> on the frontal <i>raha</i> and <i>udyotasimha</i> on each face of the <i>raha</i> . The doorjambs have three plain <i>sakhas</i> and <i>pidhamundi</i> at the base. Plain Nil The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction 11. Condition Assessment	:	Rekha vimana of Kalingan order. Ashlar dry masonry Sandstone is used both for the construction of the temple and the platform.
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Good

In Brief (Attach extra sheet if necessary):

Except the doorjambs, the temple is in a good state of preservation due to the renovation work.

12. Threats to the Property
✓ Natural Negligence Vandalism ✓ Urban Pressures x x x x x x x x x x x x x x x x x x x
SECTION III: REFERENCES
13. Reference Sources (published and unpublished textual details)
1. K. S. Behera, 2008, <i>The Lingaraja Temple of Bhubaneswar</i> , <i>Art and Cultural Legacy</i> , New
Delhi. 2. Debala Mitra, 1961, <i>Bhubaneswar</i> , ASI, New Delhi. 3.
14. Photographs: 12 nos
(attach list as in page 6, in case of multiple photographs)
Photo Reference : CAPTION :
15. Audio / Video
(related to rituals / performance / festivals etc.)
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers
NAME : Jaya Shankar Naik NAME :
18. Reviewers
NAME: Dr. S. Pradhan NAME: COMMENTS: