

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 291

	SECTION I: IDENTIFICATION	
1. Name		
Present Past Other Name (if any):		mple (Temple No 106), mplex, Bhubaneswar, Dist
2. Location		
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ² 26 N	ELEVATION 70 ft.
Address	Post: Old Town Tehsil: Bhubaneswar State: Orissa	Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	•	h of the Grand Lingaraja within in Old Town, Bhubaneswar.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures Public square	Note. The temple has a <i>pidha vimana</i> of <i>Kalingan</i> order.

4. Property Use	
Duranut	ABANDONED / IN USE: Abandoned
Present Past	Non-living temple.Worshipped
5. Age (Source)	· Wordingpod
PERIOD	: Suryavamsi Gajapati rule
YEARS	: 16 th century AD.
Precise date of Construction	:
Completion	:
Subsequent changes	: The temple was renovated and conserved by Archaeological Survey of India.
Destruction / Demolition	: Presently the <i>mastaka</i> of the temple is missing.
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE: Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Protected monument of Archaeological Survey of India
Private Any other (Please specify)	 Lingaraja Temple Trust Board Endowment Department, Government of Orissa manages the property of the temple.
Name	:
Address	: Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone	: 0674- 2558170
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify) • WITH PERSONS	:
Patron	: Archeological Survey of India and Endowment Department, Government of Orissa.
Architect / Engineer	:
Any other (specify)	: Lingaraja Temple Trust Board
8. Statement of Significance	
Architectural	✓ Architectural
Archaeological	
Historical	
Religious Any other(spedify)	: On architectural ground, the temple can be dated to the late
	Suryavamsi Gajapati rule.

<u>SE</u>	ECTION II: DESCRIPTION
9. Physical Description and Deco	
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) : No : Urban setting
Surroundings	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
• Quantification Area Dimension (L x B x H)	: 3.00 mtrs x 2.70 mtrs x 3.70 mtrs (approximate height) (m / cm/ feet / inch
Number of Blocks Number of Storys	: One : N.A.
Spatial Organization	
Orientation Plan	 Facing towards west. The <i>vimana</i> is square on plan that stands over a <i>pista</i> of 1.02 mtrs in height.
Allocation of Spaces	: 158.49 mtrs x 141.73 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE • Ornamentation	
Exteriors	: Devoid of any decoration except the image of a defaced and mutilated Ganesa in the southerr parsvadevata niche. The doorjambs have dvarapala images at the base, navagraha panel flanked by bharabahaka in the architrave and Gaja-Laxmi in the lintel.
Interiors	: Plain
Movable Collections * Any Other (specify)	NilThe temple is pancharatha on plan and panchangabada in elevation.
10. Construction Technology	
Structural System Building Techniques Material of Construction	 Pidha vimana of Kalingan order. Ashlar dry masonry Laterite is used for the construction of the temple and the pista whereas Sandstone for the doorjambs, graha panel and the veneering floor of the pista. Traces o lime plaster are found on the exterior surface of the temple.
11. Condition Assessment	
In General Good / Fair	: Fair
	eterioration Deterioration
==:::::::::::::::::::::::::::::::	-

In Brief (Attac	ch extra sheet if necessary):
The temple is	abandoned and presently used as a store room.
12. Threats to	the Property
	✓ Natural Negligence Vandalism ✓ Urban Pressures
	SECTION III: REFERENCES
13. Reference	Sources (published and unpublished textual details)
Delhi. 2. Debala M 3.	era, 2008, <i>The Lingaraja Temple of Bhubaneswar</i> , <i>Art and Cultural Legacy</i> , New litra, 1961, <i>Bhubaneswar</i> , ASI, New Delhi.
14. Photogra _l	(attach list as in page 6, in case of multiple photographs
Photo Referer CAPTION	ce :
15. Audio / Vi	
15. Audio / Vi	
Reference DESCRIPTIO	: N :
Reference DESCRIPTIOI	: N :
Reference	
Reference DESCRIPTIOI 16. Maps/Plar 17. Listers	: N :
Reference DESCRIPTIOI 16. Maps/Plar	Jaya Shankar Naik NAME :