

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No.: OR / KDA / BSR – 293

	SECTION I : IDENTIFICATION
1. Name	
Present	: Unidentified Siva Temple (Temple No 112), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda
Past Other Name (if any):	: :
2. Location	
LONGITUDE 85°50'05" E	<b>LATITUDE</b> 20 <sup>0</sup> 14 <sup>2</sup> 26 <sup>°</sup> N <b>ELEVATION</b> 70 ft.
Address	<ul> <li>Village (village code)</li> <li>Post : Old Town</li> <li>Tehsil: Bhubaneswar</li> <li>State : Orissa</li> <li>Lingaraja Temple Complex</li> <li>Via: Old Town, Bhubaneswar</li> <li>District: Khurda</li> <li>PIN: 751002</li> </ul>
Approach	: The temple, on the north of the Grand Lingaraja within the complex is situated in Old Town, Bhubaneswar.
3. Property Type	
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public building         Residential building	Religious structures       Other Structures         Image: Temple       Wall         Mosque       Gateway         Minar       Pillar         Church       Others (specify)         Monastery       Stupa         Tomb, Mausoleum
Engineering structure         Bridge         Tunnel         Other engineering structure	Open space and related structuresNote.Public squareThe temple has a pidha vimana of Kalingan order.Park or gardenof Kalingan order.GraveyardBaolis, WellTankCave

		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a circular <i>yonipith</i> without a <i>lingam</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	Ganga rule
YEARS	:	14 <sup>th</sup> century AD.
Precise date of Construction	:	
Completion Subsequent changes	÷	Now the renovation work of the temple is under
Subsequent changes	•	progress.
Destruction / Demolition	:	
6. Ownership / Level of Protectio	n	
		SINGLE /MULTIPLE : Multiple
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Archaeological Survey of India
Private	:	Lingaraja Temple Trust Board maintains the rituals of
	_	the temple.
Any other (Please specify)	÷	Endowment Department, Government of Oriss manages the property of the temple.
Name	:	
Address	:	Archaeological Survey of India, Bhubaneswar Circle 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone	:	0674- 2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Kartika Purnima, Sankranti, etc.
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS Patron	:	Archeological Survey of India and Endowmer
-		Department, Government of Orissa.
Architect / Engineer	:	
Any other (specify)	:	Lingaraja Temple Trust Board
8. Statement of Significance		
Architectural Archaeological Historical	✓	Architectural
Religious	✓	Religious
Any other(spedify)	:	On architectural ground and iconographical feature of th parsvadevata image, the temple can be dated to the lat

# SECTION II: DESCRIPTION

<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* Drawings (Attach extra sheet if necessary) : No : Urban setting
Curroundingo	Stand in IsolationComplexIntegral part of a Landscape// Street / Complex :/
Quantification	
Area Dimension (L x B x H)	: 6.00 mtrs x 5.50 mtrs x 5.25 mtrs (approximate height) ( <b>m</b> / cm/ feet / inch
Number of Blocks	: One
Number of Storys	: N.A.
Spatial Organization	
Orientation	: Facing towards west.
Plan	: The <i>vimana</i> is square on plan that stands over a <i>pist</i>
Allocation of Spaces	of 0.16 mtrs in height. : 158.49 mtrs x 141.73 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE	
Ornamentation Exteriors	. Devoid of any description execut the image of a few
Extendis	: Devoid of any decoration except the image of a fou armed Ganesa in the southern <i>parsvadevata</i> nicke The doorjambs have three <i>sakhas- lata, lata</i> an <i>puspa</i> from interior to exterior and <i>pidhamundi</i> at th base housing the images of river goddess Ganga an Yamuna along with <i>dvarapalas</i> .
Interiors	: Plain
Movable Collections	: Nil
* Any Other (specify)	: The temple is <i>pancharatha</i> on plan and <i>triangabada</i> i elevation.
10. Construction Technology	
Structural System	: Rekha vimana of Kalingan order.
Building Techniques Material of Construction	<ul><li>Ashlar dry masonry</li><li>Sandstone is used for the construction of the temple.</li></ul>
11. Condition Assessment	
In General Good / Fai	r : Good
Ŭ	Deterioration
Serious	s Deterioration

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation due to the recent renovation work.

#### **12. Threats to the Property**

$\checkmark$	Natural
	Negligence
	Vandalism
✓	Urban Pressures

## **SECTION III:** REFERENCES

- 13. Reference Sources (published and unpublished textual details)
- 1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar*, *Art and Cultural Legacy*, New Delhi.
- 2. Debala Mitra, 1961, *Bhubaneswar*, ASI, New Delhi.
- 3.

#### 14. Photographs: 05 nos

		(attach list as in page 6, in case of multiple photographs)				
Photo Referen CAPTION	ce :					
15. Audio / Vie	deo					
		(related to rituals / performance / festivals etc.)				
Reference DESCRIPTION	: I :					
16. Maps/Plans/Drawings						
17. Listers						
NAME :	Jaya Shankar Naik	NAME :				
18. Reviewers	6					

NAME : Dr. S. Pradhan COMMENTS NAME : COMMENTS :