

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / BSR - 295

1. Name	SECTION I: IDENTIFICATION
Present	: Unidentified Siva Temple (Temple No 117), Lingaraja Temple Complex, Bhubaneswar, Dist. – Khurda
Past Other Name (if any): 2. Location	: :
	0 ' "
LONGITUDE 85°50'05" E	LATITUDE 20 ⁰ 14 ² 26 N ELEVATION 70 ft.
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple, on the north-east of the Grand Lingaraja within the complex is situated in Old Town, Bhubaneswar.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note. The temple has a pidha vimana of Kalingan order.

4. Property Use ABANDONED / IN USE: Abandoned Non-living and dilapidated temple, the presiding deity Present is missing now. Worshipped **Past** 5. Age (Source) **PERIOD** Suryavamsi Gajapati rule 16th century AD. YEARS Precise date of Construction Completion Subsequent changes The temple was renovated and conserved by Archaeological Survey of India. **Destruction / Demolition** The *mastaka* of the temple is missing. 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple Protected monument of Archaeological Survey of India **Public**: Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) **Private** Lingaraja Temple Trust Board Endowment Department, Government of Orissa Any other (Please specify) manages the property of the temple. Name Address Archaeological Survey of India, Bhubaneswar Circle, 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa. **Phone** 0674-2558170 7. Association • WITH EVENTS In History In Rituals In Building Construction ---Any other (specify) WITH PERSONS Patron Archeological Survey of India and Endowment Department, Government of Orissa. Architect / Engineer Any other (specify) Lingaraja Temple Trust Board 8. Statement of Significance Architectural Architectural Archaeological

On architectural ground, the temple can be dated to the

Survavamsi Gajapati rule i.e. about the 16th century AD.

Historical Religious

Any other(spedify)

SECTION II: DESCRIPTION

		······································
9. Physical Description and Dec	corat	tive Features
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Urban setting
Ourroundings		Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
Quantification		
Area Dimension (LxBxH)	:	4.40 mtrs x 4.10 mtrs x 4.00 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks	:	One
Number of Storys	:	N.A.
 Spatial Organization 		
Orientation	:	Facing towards south.
Plan	:	The <i>vimana</i> is square on plan that stands over a <i>pista</i> of 0.58 mtrs in height.
Allocation of Spaces	:	158.49 mtrs x 141.73 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE		
 Ornamentation 		
Exteriors	:	Devoid of any decoration except a <i>khakharamundi</i> design housing Saivite <i>dvarapalas</i> at the base of the doorjambs, <i>navagraha</i> panel in the architrave and the seated Gaja-Laxmi in the lintel.
Interiors	:	Plain
Movable Collections	:	Nil
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.
10. Construction Technology		
Structural System	:	The <i>vimana</i> of the temple is <i>pidha</i> order of <i>Kalingan</i> style.
Building Techniques	:	Ashlar dry masonry
Material of Construction	:	Laterite is used for the construction of the temple and
		base of the pista whereas Sandstone for the
		doorjambs, <i>graha</i> panel and the veneering floor of the <i>pista</i> .
11. Condition Assessment		
In General Good / Fair	• :	Fair
✓ Sign of	Dete	rioration
Serious	Dete	erioration
Danger	of Di	isappearance
In Brief (Attach extra sheet if ne	eces	sary):

The temple is now used as a store house and lost its sanctity.

12. Threats to the Proper

✓ Natural
✓ Negligence
✓ Vandalism
✓ Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar*, *Art and Cultural Legacy*, New Delhi.
- 2. Debala Mitra, 1961, Bhubaneswar, ASI, New Delhi.

3.

14. Photographs: 05 nos

(attach list as in page 6, in case of multiple photographs)

Photo Reference : CAPTION :

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference : DESCRIPTION :

16. Maps/Plans/Drawings

17. Listers

NAME: Jaya Shankar Naik NAME:

18. Reviewers

NAME: Dr. S. Pradhan NAME:

COMMENTS COMMENTS: