INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

# Serial No.: OR / KDA / BSR - 300

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any): 2. Location	<ul> <li>Vrsabha Temple (Temple No 111), Lingaraja Temple Complex, Bhubaneswar, Dist Khurda</li> <li></li> <li></li> </ul>
	<b>0</b>
<b>LONGITUDE</b> 85 <sup>0</sup> 50 <sup>0</sup> 05 <sup>°</sup> E	LATITUDE 20 <sup>0</sup> 14 <sup>2</sup> 26 <sup>°</sup> N ELEVATION 70 ft.
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Lingaraja Temple Complex Via: Old Town, Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple is situated on the north of the Grand Lingaraja within the complex in Old Town, Bhubaneswar.
3. Property Type	
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public building         Residential building	Religious structures       Other Structures         ✓       Temple       Wall         Mosque       Gateway         Minar       Pillar         Church       Others (specify)         Monastery       Stupa         Tomb, Mausoleum       Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote.Public squareThe temple has a pidha vimana of Kalingan order.Park or gardenof Kalingan order.Baolis, WellTankCaveCave

		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a colossa monolithic figure of a squatting bull.
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	Ganga rule
YEARS	:	13 <sup>th</sup> century AD
Precise date of Construction	:	First half of the 13th century AD
Completion	:	
Subsequent changes	:	Renovated and conserved by Archaeological Survey o India.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
-		SINGLE /MULTIPLE : Multiple
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monument of Archaeological Survey of India
Private	:	Lingaraja Temple Trust Board maintains the rituals o the temple.
Any other (Please specify)	:	Endowment Department, Government of Orissa manages the property of the temple.
Name	:	
Address	:	Archaeological Survey of India, Bhubaneswar Circle 153 - VIP Area, Nayapalli, Bhubaneswar, Orissa.
Phone	:	0674- 2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri is performed here.
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	Archeological Survey of India and Endowmen Department, Government of Orissa.
Architect / Engineer	•	
Any other (specify)	:	Lingaraja Temple Trust Board
8. Statement of Significance		
Architectural	✓	Architectural
Archaeological		
Archaeological Historical		
Historical Religious		

On architectural ground and sculptural embellishments, the temple can be assigned to the first half of the 13th century AD i.e. the Ganga rule in Orissa.

# **SECTION II: DESCRIPTION**

### 9. Physical Description and Decorative Features

Context     Urban / Rural Setting     Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Urban setting
ourroundings		Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :
• <b>Quantification</b> Area Dimension ( L x B x H)	:	4.25 mtrs x 6.10 mtrs x 8.50 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks Number of Storys	:	One N.A.
<ul> <li>Spatial Organization</li> <li>Orientation</li> <li>Plan</li> <li>Allocation of Spaces</li> </ul>	:	Facing towards north. A square <i>vimana</i> that stands over a platform of 0.32 mtrs in height having three mouldings. 158.49 mtrs x 141.73 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE <ul> <li>Ornamentation</li> </ul>		
Exteriors Interiors Movable Collections * <b>Any Other</b> (specify)	:	Decorated with architectural motifs like <i>khakharamundis, pidhamundis</i> in the lower and upper <i>jangha</i> respectively, decorative motif like <i>vidalas</i> and <i>nayikas</i> in the recess of the <i>pagas</i> in the <i>jangha</i> , divine figures like standing Surya on a chariot drawn by four horses in the eastern balustraded window and a four-armed standing Kartikeya on the western face of the temple. The doorjambs have <i>pidhamundi</i> housing river goddess at the base and the upright block supporting the <i>navagraha</i> panel architrave have <i>pidhamundi</i> housing maithuna images and <i>dvarapalas</i> above it. Plain Nil The temple is <i>pancharatha</i> on plan and
	•	panchangabada in elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction	:	<i>Rekha vimana</i> of <i>Kalingan</i> order. Ashlar dry masonry Sandstone is used both for the platform and the

### temple.

# **11. Condition Assessment**

In General

Good / Fair : Good ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance

# In Brief (Attach extra sheet if necessary):

Though the temple is in a good state of preservation, however, a few images are eroded and mutilated.

### **12. Threats to the Property**

✓ Natural
 Negligence
 Vandalism
 ✓ Urban Pressures

# **SECTION III:** REFERENCES

### 13. Reference Sources (published and unpublished textual details)

- 1. K. S. Behera, 2008, *The Lingaraja Temple of Bhubaneswar*, *Art and Cultural Legacy*, New Delhi.
- 2. Debala Mitra, 1961, *Bhubaneswar*, ASI, New Delhi.
- 3.

# 14. Photographs: 26 nos

17. Listers	
16. Maps/Plans/Drawings	
Reference DESCRIPTION	
15. Audio / Video	(related to rituals / performance / festivals etc.)
Photo Reference CAPTION	
¥ 1	(attach list as in page 6, in case of multiple photographs)

NAME : Jaya Shankar Naik NAME :

#### 18. Reviewers

NAME : Dr. S. Pradhan COMMENTS NAME : COMMENTS :