INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

## Serial No.: OR / KDA / 02

	<u>SECTION I</u> : IDENTIFICATION		
1. Name			
Present Past Other Name (if any):	: Bhagavati Temple, Bana : :	pur Town, Dist Khurda	
2. Location			
<b>LONGITUDE</b> 85 <sup>0</sup> 10' 13" E	<b>LATITUDE</b> 19 <sup>0</sup> 46' 45" N	ELEVATION 46 ft	
Address	: Village (village code) Post : Banapur Town Tehsil: Banapur Town State : Orissa	Bhagavati Sahi, Banapur Town <b>Via:</b> Banapur Town District; Khurda PIN; 752031	
Approach		napur town in the Bhagavati kms west N.H5, leading from pur.	
3. Property Type			
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building		Other Structures         Wall         Gateway         Pillar         Others (specify):    Note. It has a pidha vimana and a khakhara inggamahana of a khakhara of	
Engineering structure         Bridge         Tunnel         Other engineering structure		<i>khakhara jagamohana</i> of impoverished <i>Kalingan</i> order.	

4. Property Use				
ABANDONED / IN USE : In use				
Present	:	It is a living temple, enshrining the image of eight- armed Mahisasuramardini Durga locally known as		
Past	:	goddess Bhagavati. Worshipped		
5. Age (Source)	-			
PERIOD	:	Modern Period( The period of Gajapati Maharaja of Puri)		
YEARS	:	19 <sup>th</sup> century A.D.		
Precise date of Construction	:			
Completion	:			
Subsequent changes Destruction / Demolition	÷	The temple premise is veneered with marble recently.		
	•			
6. Ownership / Level of Protection	on			
		SINGLE /MULTIPLE : Multiple		
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected Monument of Orissa State Archaeology and under the Endowment Department, Government of Orissa.		
Private	:			
Any other (Please specify)	:			
Name	:			
Address	:	Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa		
Phone	:	0674-2432147		
7. Association				
WITH EVENTS				
In History	:			
In Rituals	:	Durga puja is celebrated here with great pomp and rejoicing.		
In Building Construction	:			
Any other (specify)	:			
WITH PERSONS Patron		Orissa State Archaeology.		
Architect / Engineer	:			
Any other (specify)	:	Endowment Department, Government of Orissa.		
9 Statement of Significance		•		
8. Statement of Significance				
Architectural Archaeological	· ·	Architectural		
Historical	:			
Religious	✓	Religious		
Any other (specify)	:	On the basis of architectural style, the temple is assigned to the 19 <sup>th</sup> century A.D., whereas the sculptures kept inside the temple are dated to the 15 <sup>th</sup> -16 <sup>th</sup> centuries A.D.		

# SECTION II: DESCRIPTION

\_\_\_\_

## 9. Physical Description and Decorative Features

Context Urban / Rural Setting Surroundings	5 ( 5,	<b>ra sheet if necessary)</b> : No Urban setting	
Surroundings	Stand in Isolation Integral part of a Landscape / Compl Street / Complex :	ex	
Quantification			
Area Dimension (L x B x H)	: 14.15 mtrs x 9.60 mtrs x 8.00 mtrs (m / cm/ feet / ir	nch`	
Number of Blocks Number of Storys	: Two :		
Spatial Organization			
Orientation	: Facing towards west.		
Plan	jagamphana is rectangular.	the	
Allocation of Spaces	: 40.00 mtrs (L) x 60.00 mtrs (W)		
ARCHITECTURAL STYLE  Ornamentation			
Exteriors	The <i>rahapaga</i> of the <i>vimana</i> is decorated with <i>pidha</i> niche surmounted by an image of Narasimha and the rest of the <i>bada</i> is devoid of sculptural embellishments. The <i>jagamohana</i> is embellished with sculptures of divinities, <i>nayikas</i> and erotic in the upper <i>jangha</i> and <i>vidala</i> in the <i>talajangha</i> .		
Interiors	: Plain		
Movable Collections	: Mahisasuramardini Durga, Chamunda, Parvati, Kartikeya, Ganesa, Herostone etc.		
* Any Other (specify)	: The temple is <i>pancharatha</i> on plan <i>panchangabada</i> in elevation.	and	
10. Construction Technology			
Structural System	: <i>Pidha vimana</i> & khakhara jagamohana impoverished <i>Kalingan</i> order.	0	
Building Techniques Material of Construction	<ul> <li>Ashlar masonry</li> <li>Stone with cement plaster.</li> </ul>		
11. Condition Assessment			
In General Good / Fair	: Good		
Sign of Deterioration Serious Deterioration Danger of Disappearance			

#### In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation.

#### **12. Threats to the Property**

Natural
 Negligence
 Vandalism
 Urban Pressures

### **SECTION III:** REFERENCES

**13. Reference Sources** (published and unpublished textual details)

1. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. - I, Delhi.

2.

### 14. Photographs: 27 nos

	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	:
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	:
16. Maps/Plans/Drawings	

17. Listers					
NAME :	D. B. Garnayak	NAME :			
18. Reviewers					
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :			