搟

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / 17 **SECTION I: IDENTIFICATION** 1. Name Present Nilakanthesvara Temple, Kotavidyadharpur (Banapur N.A.C), Dist. - Khurda **Past** Other Name (if any): 2. Location **LONGITUDE** 85⁰ 10' 07" E 19⁰ 47' 21" N LATITUDE **ELEVATION** 60 ft **Address** Village (village code) Kotavidyadharpur (Banapur N.A.C.) Via: Banapur Post: Banapur Tehsil: Banapur District: Khurda State: Orissa PIN: 752031 **Approach** The temple is located on the left side of the road leading from Banapur to Sana-Hantuad, branching at a distance of one km from Pandiripadara chowk. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify): Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Note. Residential building The temple has a rekha vimana and a flat-roofed mandapa of Engineering structure Open space and related Kalingan order. structures Bridge Public square Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the presiding deity is a Sivalinga within a circular <i>yonipitha</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	:::::::::::::::::::::::::::::::::::::::	Late Somavamsi rule 11 th century A.D. Last quarter of the 11 th century AD Renovated by the Village Temple Committee.
6. Ownership / Level of Protection	<u>n</u>	SINGLE /MULTIPLE : Multiple
Dublic - Archeological Company of		SINGLE/MOLTIPLE: Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify)	:	Village Temple Committee under the presidentship of Prabhasa Chandra Hota.
Name	:	
Address Phone	:	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : : : : : : : : : : : : : : : : :	Sivaratri, Kartika Purnima, etc are observed here. Thread ceremoney is held here. Village Temple Committee

ŏ	. Statement of Significance		
	Architectural	✓	Architectural
	Archaeological	:	
	Historical	:	
	Religious	/	Religious
	Any other (specify)	:	On architectural ground and use of building material, the temple can be assigned to the last quarter of the 11 th century AD. i.e. the late Somavamsi rule in Orissa.

SECTION II: DESCRIPTION

9. Physical Description and De	corat	ive Features	
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary): No Rural setting	
· ·		Stand in Isolation Integral part of a Landscape / Street Street / Complex :	
• Quantification Area Dimension (L x B x H)	:	14.25 mtrs x 7.70 mtrs x 15.00 mtrs (approximate height)	
Number of Blocks Number of Storys	:	(m / cm/ feet / inch) Two (<i>vimana</i> and a flat-roofed <i>mandapa</i>) N.A	
Spatial Organization			
Orientation Plan	:	Facing towards west. The <i>vimana</i> is square on plan and the <i>mandapa</i> in front is rectangular.	
Allocation of Spaces	:	50.00 mtrs (L) x 43.25 mtrs (W)	
ARCHITECTURAL STYLE Ornamentation			
Exteriors	:	Devoid of any decoration, except the <i>deulacharinis</i> and <i>dopichhasimhas</i> over the <i>beki</i> to support the <i>amlasila</i> , a miniature <i>rekhamudi</i> in the frontal <i>raha</i> and the <i>talagarbhika</i> is in <i>rekahamundi</i> design whereas the <i>urdhagarbhika</i> is a <i>pidhamundi</i> flanked by <i>khakharamundis</i> .	
Interiors	:	Plain	
Movable Collections	:	Images of Ganesa, Katikeya, Parvati, female divinity, etc.	
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan and <i>panchangabada</i> in elevation.	
10. Construction Technology			
Structural System Building Techniques Material of Construction	: :	Rekha vimana of Kalingan order. English bond technique with lime mortar. Bricks (0.37 / 0.32 mtrs x 0.20 /0.22 mtrs x 0.06 mtrs in dimension) are used for the construction of the temple and now the entire surface is applied with red wash.	
11. Condition Assessment			
In General Good / Fair	:	Fair	
✓ Sign of Deterioration Serious Deterioration			

Growths of year	etation like pipal trees a	are noticed on the frontal <i>raha</i> of the temple.
J		no noticed on the nontal fund of the temple.
12. Threats to	the Property	1
	✓	Natural Negligence
		Vandalism
		Urban Pressures
XXXXXX	X X X X X X X X X X X	××××××××××××××××××××××××××××××××××××××
	SECT	ION III: REFERENCES
13 Pafaranca	Sources (nublished and	d unpublished textual details)
1	Jources (published and	d dripublished textual details)
2.		
14 Dhotogran	ho	
14. Photograp	115	(attach list as in page 6, in case of multiple photographs
Photo Referen	ice :	
CAPTION	:	
15. Audio / Vic	leo	
		(related to rituals / performance / festivals etc.
Reference	:	
DESCRIPTION	:	
16. Maps/Plan	s/Drawings	
47 Lintana		
17. Listers		
NAME:	Jaya Shankar Naik	NAME: