

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/MBJ- 08 **SECTION I: IDENTIFICATION** 1. Name Present Chandrasekhar Mahadev Temple, Khiching, Dist. - Mayurbhani **Past** Other Name (if any): 2. Location **LONGITUDE** 85° 49′ 58″ E 21⁰ 55['] 39["] N LATITUDE **ELEVATION** 1220 ft **Address** Village (village code) Khiching Post: Khiching Via: Sukruli Tehsil: Karanjia **District:** Mayurbhanj. State: Orissa PIN: 757039 Approach It is located 13 km. north of the national Highway No.06, from Singda Chowk and it is about 20mtrs south-west corner of Kichakesvari Temple. 3. Property Type Religious structures Other Structures Buildings Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures It is a *rekha* temple with a regional Bridge Public square style of architecture of the Bhanja. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use ABANDONED / IN USE: In use Present It is a living temple enshrining a Sivalinga within a circular yonipitha of two moulding and made of chlorite. **Past** Worshipped. 5. Age (Source) Bhanja rule of Khijjinga Mandala. PERIOD **YEARS** 9th– 10th centuries A.D. 9th – 10th centuries A.D. **Precise date of Construction** Completion Subsequent changes Thoroughly renovated by the Bhanjas of Mayurbhanj. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : India State Archaeology Protected Monument of Orissa State Archaeology and / Department / Any Other (Please Endowment Department, Government of Orissa specify) Private Any other (Please specify) Name Address Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa **Phone** 0674-2432147 7. Association WITH EVENTS In History Sivaratri and Kartika Purnima. In Rituals In Building Construction : It was built by Bhanjas of Khijjinga Mandala. Any other (specify) WITH PERSONS Patron Originally, the Bhanjas of Khijjinga Mandala but now Orissa State Archaeology is looked after the monument. Architect / Engineer Any other (specify) Kichakesvari Temple Trust Board 8. Statement of Significance Architectural ✓ Architectural Archaeological Historical Religious

The architectural features and pabhaga mouldings assign

Any other (specify)

the temple to the 9th -10th centuries A.D.

SECTION II: DESCRIPTION

• Context	* Drawings (Attach extra sheet if necessary): No	
Urban / Rural Setting Surroundings	: Rural setting	
3	Stand in Isolation Integral part of a Complex Landscape / Street / Complex:	
• Quantification Area Dimension (L x B x H)	: 3.85 mtrs X 3.55 mtrs X 8.00 mtrs	
Number of Blocks Number of Storys	(m / cm/ feet / inch) : Single. :	
 Spatial Organization Orientation Plan Allocation of Spaces 	The temple is facing towards east.The <i>vimana</i> is square on plan.1714sq.fts.	
• Ornamentation Exteriors	The temple is devoid of sculptural emblishments but the jangha is decorated with architectural motifs like extensions. The extensions of the piloteter decigns. The extensions are the extensions of the piloteter decigns.	
	octagonal and flat pilaster designs. The octagonal pilasters are based over a <i>khura</i> like moulding which are surmounted by <i>kalasa(ghata)</i> . The pilaster's shafts are octagonal and crowned with three mouldings.	
Interiors Movable Collections	 Plain. Architectural members like <i>amlaka</i>, base mouldings and two hero stones at the pathway near the entrance of the temple. 	
* Any Other (specify)	: The temple is <i>triratha</i> on plan and <i>triangabada</i> in elevation.	
10. Construction Technology	у	
Structural System	: Rekha vimana of Kalingan order with a regional Bhanja style of decoration.	
Building Techniques Material of Construction	: Ashlar dry masonry.: Black chlorite	
11. Condition Assessment		
In General Good / Fair	: Good.	
Sign of Deterioration Serious Deterioration		

Danger o	f Disappearance	
In Brief (Attac	ch extra sheet if ne	cessary):
The temple war missing.	as renovated from th	ne <i>bada</i> portion to the <i>mastaka</i> . The <i>graha</i> panel is partia
12. Threats to	the Property	
x	. x x x x x x x x x x	✓ Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
	SI	ECTION III: REFERENCES
13 Reference	Sources (nublished	d and unpublished textual details)
Photo Reference CAPTION	nce	(attach list as in page 6, in case of multiple photogra
15. Audio / Vi	deo	(related to rituals / performance / festivals
Reference DESCRIPTION	N	; ;
16. Maps/Plar	ns/Drawings	
17. Listers		
NAME:	D. B. Garnayak	NAME:
18.Reviewers		
NAME:	Dr. S. Pradhan	NAME: