

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/MBJ- 13 **SECTION I: IDENTIFICATION** 1. Name Present Kakharua Baidyanath Temple, Manatri, Dist. - Mayurbhani **Past** Other Name (if any): 2. Location **LONGITUDE** 86° 48′ 30″ E LATITUDE 21⁰ 38['] 41["] N **ELEVATION** 45 ft Address Village (village code) Manatri Post: Manatri Via: Badasahi Tehsil: Badasahi **District:** Mayurbhani State: Orissa **PIN**: 757012 It is 45 kms south east of Baripada town and 12 kms Approach from Baisinga on the Baisinga - Udala road. It is located on the right bank of the Budhabalanga river at a distance of 4 kms. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Pillar Citadel Minar Govt. building Others (specify)-Church Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures It has a pancharatha rekha Bridge Public square vimana followed by a pidha Tunnel Park or garden jagamohan and natamandapa Other engineering structure Graveyard of Kalingan order. Baolis, Well Tank Cave

4. Property Use ABANDONED / IN USE: In use **Present** Living temple. The presiding deity is a Sivalinga within a circular yonipitha. **Past** Worshipped. 5. Age (Source) **PERIOD** Bhanja rule of Khijjingakota 15th century A.D. YEARS 15th century A.D. Precise date of Construction Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE: Multiple **Public**: Archaeological Survey of : Endowment Department, Government of Orissa. India State Archaeology Department / Any Other (Please specify) **Private** Any other (Please specify) It is under the care and maintenance of Kakharua Baidyanath Puja Committee. Name **Address** At/PO-Manatri, Tehesil - Badasahi, P.S.-Baisinga, Dist. - Mayurbhani, Pin-757017 **Phone** 7. Association WITH EVENTS As per the temple records, the temples was built by In History Kakharua Dev of Bhanja dynasty in 15th century A.D. Sivaratri. Sitalasathi. Kartika Purnima etc are In Rituals observed. In Building Construction Any other (specify) Marriage, thread ceremony, etc are performed. WITH PERSONS Endowment Department, Government of Orissa. Patron **Architect / Engineer** Any other (specify)

Architectural

Historical

Religious

8. Statement of Significance

Architectural

Religious

Archaeological Historical

Any other (specify)		On the basis of the architectural feature and temple records,
		the temple can be assigned to 15th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context

Urban / Rural Setting

Surroundings

* **Drawings** (Attach extra sheet if necessary): No

Rural Setting

Complex

Stand in Isolation Integral part of a Landscape / Street /

Complex:

Quantification

Area Dimension (L x B x H) : 31.60 mtrs x 9.80 mtrs x 19.36 mtrs

(m / cm/ feet / inch)

Number of Blocks : Three Number of Storys : ---

:

• Spatial Organization

Orientation : Facing towards east.

Plan : Vimana is square on plan whereas jagamohana and

natamandapa are rectangular.

Allocation of Spaces : 57.00 mtrs x 41.35 mtrs in length and breadth

respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Plain Interiors : Plain

Movable Collections : Four-armed Visnu, Astikajaratkura, *Matrika* and

Deulacharini image etc.

* Any Other (specify) : As per the architectural style and decoration it seems that

the present temple is a renovated one over an ancient

temple.

10. Construction Technology

Structural System : The temple has three structures. The vimana is of

pancharatha rekha type whereas jagamohana and dancing hall are of rectangular pidha type temple. On elevation vimana has panchangabada and rests two have

triangabada.

Building Techniques : Ashlar dry masonary

Material of Construction : Sandstone

11. Condition Assessment

In General Good / Fair : Good

-- | Sign of Deterioration

Danger of	eterioration Disappearance n extra sheet if ned	cessary):				
•	tate of preservation	• •				
12. Threats to	the Property					
x x x x x x x x	x x x x x x x x x x S E	Van Urba x x x x x	ligence dalism an Pressures		: x x x x x x :	x
13. Reference	Sources (published	d and unn	ublished textua	ıl details)		
4 M.N.Vasu,	i (ed.) 1967, <i>Orissa</i> 1911, <i>Archaeologid</i> dson, 1986, <i>Hindu</i> T	cal Survey Temple Ar	√ of Mayurbhan	j, Mayurbha II, London	anj State.	ohotographs)
Photo Referen	ce	:				
CAPTION		:				
15. Audio / Vid	eo		/== = t = = t .	- miturala / m -	fo	fa a 4: , , a la _ a 4 a _ \
Reference DESCRIPTION		:	(related to	o niluais / pe	enormance / 1	festivals etc.)
16. Maps/Plans	s/Drawings					
17. Listers						
NAME :	D. B. Garnayak		NAME :			
18.Reviewers	·					
	Dr. S. Pradhan		NAME : COMMENTS :			