

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/MBJ-06 **SECTION I: IDENTIFICATION** 1. Name Present Radha Mohan Temple, Haripurgarh, Dist - Mayurbhani Past Other Name (if any): 2. Location **LONGITUDE** 86° 42′ 56″ E 21⁰ 48['] 14["] N LATITUDE **ELEVATION** 60 ft **Address** Village (village code) Haripur, Ward No-5 Post: Haripur Via: Pratapapur **District**: Mayurbhanj Tehsil: Badasahi State: Orissa **PIN:** 757103 Approach The temple is located within the fortified area of Haripurgarh, in the north-west direction of Rasikaraya temple. The Haripurgarh is 15 kms north-west of Baripada town of Mayurbhani district. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Others (specify) Church Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures It has a square sanctum followed Bridge Public square by a rectangular mandapa. It was Tunnel Park or garden built by Raja Vira Vikramaditya Other engineering structure Graveyard Bhanja, Bhanja ruler of Baolis, Well Khijjingakota. Tank Cave

4. Property Use

ABANDONED / IN USE: Abandoned

Present : It is a nonliving temple.

Past : Worshipped

5. Age (Source)

PERIOD : Bhanja rule of Khijjingakota

YEARS : 16th century A.D Precise date of Construction : 16th century A.D

Completion : -

Subsequent changes : Renovated and repaired by Archaeological Survey of

India

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE / MULTIPLE : Single

Public: Archaeological Survey of : Protected Monument of Archaeological Survey of India / State Archaeology India.

Department / Any Other (Please

specify)

Private : --Any other (Please specify) : ---

Name

Address : Archaeological Survey of India, BhubaneswarCircle,

153, VIP Area, Nayapalli, Bhubaneswar, Orissa

Phone : 0674-2558170

7. Association

WITH EVENTS

In History : --In Rituals : ---

In Building Construction : The temple was commissioned by Raja Vikramaditya

Bhanja.

Any other (specify) : --

WITH PERSONS

Patron : Originally by the Bhanjas of Khijjingakota but now

Archaeological Survey of India is taken care of the

monument.

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance

Architectural	\checkmark	Architectural
Archaeological		
Historical	✓	Historical
Religious		
Any other (specify)	:	On the basis of epigraphical records and architectural

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context

Urban / Bural Satting

Urban / Rural Setting Surroundings

etting

* **Drawings** (Attach extra sheet if necessary):

Rural setting

Complex

No

Stand in Isolation

Integral part of a Landscape

/ Street / Complex :

Quantification

Area Dimension (L x B x H) : 17.15 mtrs x 6.60 mtrs x 2.70 mtrs(existing height)

(m / cm/ feet / inch)

Number of Blocks : Two, consists a sanctum and a *jagamohana*.

Number of Storys : -

:

• Spatial Organization

Orientation : Facing towards east.

Plan : It has a square sanctum and rectangular jagamohana

that stands over a 0.90 mtrs high platform.

Allocation of Spaces : 40.00 mtrs x 25.30 mtrs in length and width

respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Both exterior and interior are plain, except few niches

are relieved in the interior walls and lime plaster

patches are evidenced both in platform and wall.

Interiors

Movable Collections : -

* Any Other (specify) : It has a square sanctum with a rectangular crown seat

(pedestal) at the centre. The sanctum is followed by a rectangular *mandapa* which has six entrances. The sanctum has two entrances, one each on east and

south.

10. Construction Technology

Structural System : The temple has lost its supper structure. Hence it is

difficult to ascertain the structural design of the temple

with any architectural style.

Building Techniques : English Bond

Material of Construction : Bricks

11. Condition Assessment

In General Good / Fair : Good

-- Sign of Deterioration

	Deterioration f Disappearance	
	ch extra sheet if nec	essary):
Though the su state of preser 12. Threats to	vation.	emple is already gone, the surviving portions are in a good
x	[.xxxxxxxxxxx	✓ Natural Negligence Vandalism Urban Pressures ⟨ x x x x x x x x x x x x x x x x x x
	<u>SE</u>	CTION III: REFERENCES
12 Potoronos	Sources (published	and unpublished toytual details)
		and unpublished textual details)
	•	ology in Orissa, Vol. II, New Delhi.
2. P.K.Mishra	a, 1997, Archaeology	of Mayurbhanj, No-1, New Delhi.
14. Photograp	ohs: 05 nos	
		(attach list as in page 6, in case of multiple photograph
Photo Refere	nce	:
CAPTION		:
15 Audio / Vi	400	
15. Audio / Vi	aeo	(related to rituals / performance / festivals etc
Reference		
DESCRIPTION	N.	•
	•	
16. Maps/Plar	ıs/Drawings	
17. Listers		
	A.R.Sahoo	NAME :
NAME:	A.IX.Salibu	NAME.
NAME: 18.Reviewers		NAME.