

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/SBP- 08 **SECTION I: IDENTIFICATION** 1. Name Present Gopalji Matha Temple, Sambalpur Town, Dist.-Sambalpur **Past** Other Name (if any): 2. Location **LONGITUDE** 83° 57′ 38″ E 21⁰ 28['] 24["] N **ELEVATION** 490feet. LATITUDE **Address** Village (village code) Kamli Bazar Post: Bada Bazar Via: Sambalpur Town **Tehsil:** Sambalpur Town **District:** Sambalpur PIN: 768003 State: Orissa **Approach** The temple, on the left bank of the river Mahanadi is located at Kamil Bazar at a distance of 3 kms north of Sambalpur Railway Station. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Others(specify): Government building Church Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Bridge Public square Tunnel Park or garden Note: Other engineering structure Graveyard The vimana and jagamohana of the temple displays the Khakhara Baolis, Well pattern of architecture. Tank Cave

4. Property Use ABANDONED / IN USE : In use Present Living temple, the enshrining deity is lord Krisna and his consort Radha which is locally known as Gopalji temple. Past Worshipped 5. Age (Source) Chauhan rule of Sambalpur State. PERIOD **YEARS** 17th century A.D. **Precise date of Construction** Built by the saint prince Bansigopal, the son of 4th Chauhan Raja Madhukara Deva (1630-1650A.D.) Completion Subsequent changes Entire surface of the temple was plastered and white washed later on. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Endowment Department, Government of Orissa. State Archaeology Department / Any Other (Please specify) Private Gopalji *Matha* Temple under the Mahanta Hrushikesa Any other (Please specify) Das. Name AT- Kamali Bazar, P.O.-Bada Bazar, Dist.-Sambalpur, Address Pin-768003, Orissa. **Phone** 7. Association WITH EVENTS In History Rathayatra, Dola Purnima, Rakhi Purnima, etc. In Rituals In Building Construction Any other (specify) **WITH PERSONS** Patron Gopalji *Matha* Temple Architect / Engineer Any other (specify) Originally the Chauhans, but presently under the care of Endowment Department, Government of Orissa. 8. Statement of Significance Architectural Architectural Archaeological

Historical.

Historical Religious

Any other (specify)	:	On architectural feature and literary evidence the temple can be dated to the second quarter of the 17 th century A.D. i.e. the Chauhan rule of Sambalpur.		
SECTION II: DESCRIPTION				
9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary): No Urban Setting		
		Stand in Isolation Integral part of a Landscape / Complex Street / Complex :		
• Quantification Area Dimension (L x B x H)	:	19.15 mtrs X 13.45 mtrs X 11.00 mtrs (approximately) (m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	Two, consists of a <i>vimana</i> and a <i>jagamohana</i> . NA		
 Spatial Organization 				
Orientation Plan	:	Facing towards east. The <i>vimana</i> is square on plan and the <i>jagamohana</i> is oblong.		
Allocation of Spaces	:	150.00 mtrs. X 38.00 mtrs in length and breadth respectively.		
ARCHITECTURAL STYLE • Ornamentation				
Exteriors	:	Devoid of sculptural embellishment, except the niches in the <i>jangha</i> portion of the wall that houses vaisnavite images.		
Interiors Movable Collections	:	Plain Images of Visnu and Sarasvati on a detached doorjambs.		
* Any Other (specify)	:			
10. Construction Technology				
Structural System	:	The santum has two subsidiary lateral chambers on either sides opening to the oblong hall of the <i>jagamohana</i> of impoverished <i>khakhara</i> order.		
Building Techniques Material of Construction	:	Ashlar masonry and English bond with lime mortar. Stone and bricks are used for the structure and the entire surface is plastered and white washed.		
11. Condition Assessment				
In General	Good / Fair : Good. Sign of Deterioration Serious Deterioration Danger of Disappearance			
In Brief (Attach extra sheet if necessary):				
The temple is in a good state of preservation.				

12. Threats to the P	roperty	
	Ne Va	itural gligence ndalism ban Pressures
X x		X X X X X X X X X X X ION III: REFERENCES published textual details)
S.Pradhan (ed.) 2. S.P.Das, 1969, 3. R.P.Mohapatra, 4. B.K.Rath (ed.), 5. N.Senapati (ed.)	Art and Archaeology of Sambalpur Itihas (Oriy 1986, Archaeology ii 1996, The Forgotton	va,) Sambalpur. n Orissa, Vol II, Delhi. Monuments of Orissa, New Delhi. ict Gazetteer, Sambalpur, Cuttack.
14. Photographs: 27	7 nos	
		ach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	: :	
15. Audio / Video		
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	: :	
16. Maps/Plans/Dra	wings	
17. Listers		
	Garanayak	NAME :
18.Reviewers		
NAME: Dr. S COMMENTS	. Pradhan	NAME : COMMENTS :