

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

	Serial No.: OR/SBP- 03
	ECTION I: IDENTIFICATION
1. Name	
Present	: Kapilesvara Temple, Huma, Dist Sambalpur
Past Other Name (if any):	:
. •	·
2. Location	
LONGITUDE 83° 54′ 46″ E	LATITUDE 21 ⁰ 16 ['] 50 ["] N ELEVATION 426 ^{ft}
Address	: Village (village code) Post: Dhama Tehsil: Sambalpur Town State: Orissa PIN: 768113
Approach	: The temple is within the Bimalesvar temple precinct at Huma, which is located on the left bank of the river Mahanadi at the confluence with Dhuli jor. It is situated at a distance of 30 kms south-east of Sambalpur town and 5 kms from Bhiropali chowk branching from the N.H. 15 leading from Sambalpur to Birmaharajpur.
3. Property Type	
Buildings Palace Fort Citadel Government building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others(specify):
Engineering structure	Open space and related structures
Bridge Tunnel Other engineering structure	Public square Park or garden Graveyard Baolis, Well Tank Cave Public square Note: The temple has a small leaning rekha vimana and devoid of sculptural embellishment and designed after the main temple Bimalesvara.

4. Property Use		
Present Past 5. Age (Source)	:	ABANDONED / IN USE: In use It is a living temple and the presiding deity is a Sivalinga within a circular yonipitha. Worshipped
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: : : :	Chauhan rule of Sambalpur State 17 th century A.D Interior as well as exterior of the temple have been plastered and lime washed later on
		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please	:	Protected monument of Orissa State Archaeology and under the Endowment Department, Government of Orissa.
specify) Private Any other (Please specify) Name	:	Huma Temple Managing Committee.
Address Phone	:	Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswara, Orissa. 0674-2432147
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron 	: : : : : : : : : : : : : : : : : : : :	Sivaratri, Kartika Purnima, Chandana Yatra, etc Originally the Chauhans, but presently under the care
		of Orissa State Archaeology and under the Endowment Department, Government of Orissa.
Architect / Engineer Any other (specify) 8. Statement of Significance	:	 Huma Temple Managing Committee
Architectural Archaeological Historical Religious		Architectural Archaeological
Any other (specify)	:	On architectural ground, the temple can be assigned to the 17 th century A.D. i.e. the Chauhan rule of Sambalpur.

SECTION II: DESCRIPTION

9. Physical Description and D	ecorative Features
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary): No : Rural setting
J	Stand in Isolation Integral part of a Complex Landscape / Street / Complex :
Quantification	
Area Dimension (LxH)	: 2.45 mtrs X 2.05 mtrs X 4.60 mtrs
Number of Blocks	(m / cm/ feet / inch) : One
Number of Storys	:
Spatial Organization	
Orientation Plan	: The temple is facing towards west.
Allocation of Spaces	The <i>vimana</i> is square on plan.65.00 mtrs X 36.50 mtrs in length and breadth respectively.
ARCHITECTURAL STYLE • Ornamentation	
Exteriors	: The temple is plain and devoid of sculptural
	embellishments.
Interiors Movable Collections	: Plain :
* Any Other (specify)	 The temple is pancharatha on plan and triangabada in elevation.
10. Construction Technology	ogy
Structural System	: It has a <i>rekha vimana</i> of Chauhan style.
Building Techniques	: Ashlar masonry with lime mortar.
Material of Construction	 Granite stone and use of lime plaster and white wash in the exterior and interior walls.
11. Condition Assessment	
In General	Good / Fair : Good
	Sign of Deterioration
	Serious Deterioration
	Danger of Disappearance
In Brief (Attach extra sheet	if necessary):
The temple is in a good state 12. Threats to the Property	·
	✓ Natural
	Negligence
	Vandalism
	Urban Pressures

 X x

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. P.K.Nayak, 2006, Temples of Western Orissa, Phase-II: Medieval Temples, in S.Pradhan (ed.) *Art and Archaeology of Orissa*, New Delhi.
- 2. R.P.Mohapatra, 1986, Archaeology in Orissa, Vol.-II, Delhi.
- 3. S.P.Das, 1969, Sambalpur Itihas(Oriya), Sambalpur.
- 4. B.K Rath (ed.), 1996, The Forgotten Monuments of Orissa, Vol.-III, New Delhi.

14. Photograp	hs: 04 nos			
		(attach list as in page 6, in case of multiple photographs)		
Photo Referen	ce	:		
CAPTION		:		
15. Audio / Vi	deo			
		(related to rituals / performance / festivals etc.)		
Reference		:		
DESCRIPTION	N	:		
40 14 (5)	.			
16. Maps/Plan	is/Drawings			
17. Listers				
NAME :	D.B. Garnayak	NAME :		
	,			
18.Reviewers				
NAME :	Dr. S. Pradhan	NAME :		
COMMENTS		COMMENTS:		