

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

		<u> </u>
1. Name	SECTION I: IDENTIFICATION	I
Present Past Other Name (if any): 2. Location	: Pancharatha Temple, S : :	onepur Town, DistSuvarnapur
<b>LONGITUDE</b> 83° 54′ 30″ E	<b>LATITUDE</b> 20 <sup>0</sup> 50 <sup>'</sup> 05 <sup>"</sup> N	<b>ELEVATION</b> 365 ft
Address	: Village (village code) Post : Sonepur Town Tehsil: Sonepur Town State : Orissa	Sonepur Town (Bus Stand) Via: Sonepur Town District: Suvarnapur PIN: 767017
Approach		close to the Sonepur town bus ght bank of the river Mahanadi.
3. Property Type		
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify)
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: Rekha temple having curvilinear superstructure of colonial period, which can be attested from the architectural style and decorative motifs.

4. Property Use						
	ABANDONED / IN USE: In use					
Present	:	It is a living temple, enshrines the image of lord Siva.				
Past	:	Worshipped.				
5. Age (Source)						
PERIOD	:	Chauhan rule of ex-Sonepur state.				
YEARS	:	Early part of the 20 <sup>th</sup> century A.D.				
Precise date of Construction	:	1935 A.D.				
Completion	:	<b></b>				
Subsequent changes	:	<b></b>				
Destruction / Demolition	:					
6. Ownership / Level of Protecti	on					
	-	SINGLE /MULTIPLE : Multiple				
Public : Archaeological Survey of	:					
India / State Archaeology						
Department / Any Other (Please						
specify)						
Private	: Pancharatha Temple Committee, Sonepur					
Any other (Please specify)	:	<b></b>				
Name	:					
Address	:	Sonepur Town, Dist Suvarnapur, Orissa, Pin-767017				
Phone	:					
7. Association						
WITH EVENTS						
In History	:	Related with the history of king Biramitra Deo.				
In Rituals	:	Sitalsasthi, Sivaratri				
In Building Construction	:					
Any other (specify)	:					
<ul> <li>WITH PERSONS</li> </ul>						
Patron	:	Pancharatha Temple Committee				
Architect / Engineer	:					
Any other (specify)	:					
8. Statement of Significance						
Architectural	<b>✓</b>	Architectural				
Archaeological	:					
Historical	/	Historical				
Religious	/	Religious				
Any other (specify)	:	The architectural style, decorative motifs and local information assign an early date of 20 <sup>th</sup> century A.D.				

## SECTION II: DESCRIPTION

9. Physical Description and De	corat	ive Features					
Context Urban / Rural Setting Surroundings		* <b>Drawings</b> (Attach extra sheet if necessary): No Urban setting					
-		Stand in Isolation Integral part of a Landscape / Street / Complex :	Street				
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	:	16.00 mtrs x 14.00 mtrs x about 1	2.00 mtrs (m / cm/ feet / inch)				
Number of Blocks Number of Storys	:	Five 	(III / GIII/ ICCC / IIIGII)				
<ul> <li>Spatial Organization         Orientation         Plan         Allocation of Spaces     </li> </ul>	: : :	Facing towards east. The temple is square on plan 35.00 mtrs x 27.55 mtrs in length a respectively.	and breadth				
• Ornamentation		5					
Exteriors Interiors	:	Decorated with stucco works hav as well as with usual temple decor Plain					
Movable Collections  * Any Other (specify)	:	The temple is built in a concept where the central one housed lo subsidiary structures house the i Ganesa, Parvati and Nandi.	rd Siva and the rest				
10. Construction Technology		The Assertation of the Islands					
Structural System	:	The temple is the lonely specime region. It consists of five cella into each other as well as providentrance. The central cella house Siva and the rest of Ganesa, Kandi in the south, west, north respectively	ernally connecting to des with individual es the image of lord artikeya, Parbati and				
Building Techniques Material of Construction	:	Ashlar masonry with English bond Bricks, stone and lime plaster.					
11. Condition Assessment							
In General	G	ood / Fair : Fair					
	<b>√</b>	Sign of Deterioration Serious Deterioration Danger of Disappearance					
In Brief (Attach extra sheet if n	ecess	sary):					
The temple is facing histical three	at lika	hirds problem. Thousands of Davo	make it's their neet				

The temple is facing biotical threat like birds problem. Thousands of Dove make it's their nest. **12. Threats to the Property** 

		✓ ✓	Vano	ıral ligence dalism an Press	ures					
X x	x x	x	X	x	x	x	х	X	x	х
		SEC	TION II	II: REFI	EREN	CES				
13. Reference	<b>e Sources</b> (pul	blished ar	nd unpu	ublished	textua	details	s)			
1.										
14. Photogra	phs: 06 nos									
-			(attac	ch list as	in pag	e 6, in	case of	multiple	e photo	graphs)
Photo Referer	nce	:								
CAPTION		:								
15. Audio / Vi	ideo									
				(re	ated to	rituals	/ perfor	mance	/ festiv	als etc.)
Reference		:								
DESCRIPTIO	N	:								
16. Maps/Pla	ns/Drawings									
17. Listers										
NAME :	D.B. Garnay	ak		NAME	:					
18.Reviewers	<b>3</b>									
NAME : COMMENTS	Dr. S. Pradha	an		NAME : COMME	NTS:					