



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/ALR-228

SECTION I : IDENTIFICATION

1. Name

Present : Panhari Well
 Past :
 Other Name (if any): :

2. Location

LONGITUDE

LATITUDE

Address

Bhangarh, Alwar

: **Village (village code)**

Post : Gola Ka Was

District: Alwar

State : Rajasthan

PIN: 301410

Approach

: The well is situated at Bhangarh in Alwar district. It is 80 Km away from Alwar. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: This is deep cylindrical water reservoir and is surrounded by elevated platform.

4. Property Use

ABANDONED / IN USE : In Use

Present : Drinking water
Past :

5. Age (Source)

PERIOD : 17th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** : Well
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | | |
|-------------------------------------|---------------------|-----------------|
| <input checked="" type="checkbox"/> | Architectural | Water reservoir |
| <input type="checkbox"/> | Archaeological | |
| <input type="checkbox"/> | Historical | |
| <input type="checkbox"/> | Religious | |
| <input type="checkbox"/> | Any other (specify) | |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | |
|------------------------------|---|
| Context | * Drawings (Attach extra sheet if necessary) |
| Urban / Rural Setting | Rural |
| Surroundings | Stand in Isolation
Integral part of a Landscape / Street / Complex |

- | | |
|--------------------------------|-----------------------|
| Quantification | |
| Area Dimension (L x B x H) : | (m / cm/ feet / inch) |
| Number of Blocks : | |
| Number of Storys : | |

- | | |
|-----------------------------|--|
| Spatial Organization | |
| Orientation : | The well is oriented East/West and faces the West. |
| Plan : | |
| Allocation of Spaces : | |

ARCHITECTURAL STYLE

- | | |
|------------------------------|----------------|
| Ornamentation | |
| Exteriors : | Bricks & Stone |
| Interiors : | |
| Movable Collections : | |
| Any Other (specify) : | |

10. Construction Technology

- | | |
|---------------------------------|--------------------------------------|
| Structural System | : Hydraulic system |
| Building Techniques | : Cylindrical water shaped reservoir |
| Material of Construction | : Trabeate & Arcuate |

11. Condition Assessment

In General	Good / Fair
	Good

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS