



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-024

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Sonaro Ki Sati Mata Mandir  
 Past :  
 Other Name (if any):

#### 2. Location

LONGITUDE 75°28'E

LATITUDE 25°58'N

#### Address

Holike Than Tejaji Chowk road, Bhilwara

: **Village (village code)**

**Post:** Bhilwara

**District:** Bhilwara

**State:** Rajasthan

**PIN:** 311001

#### Approach district

: The Temple is situated at Teja Jee Chowk road in Bhilwara district. It is 2km away from Bus stand. it is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This shrine is raised on a platform and can be accessed through a set of stairs. It has a round arched gate opening with a profusely carved façade. Which is rafter with a domical sprine? This is followed with an open and pillared mandapa that leads to the sanctum which is octagonal in plan. The main shrine has bigger dome roof.

#### 4. Property Use

---

**ABANDONED / IN USE**

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 20<sup>th</sup> Century AD  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE / MULTIPLE :**

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)state Govt.

**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                |
|-------------------------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural  |
| <input type="checkbox"/>            | Archaeological |
| <input type="checkbox"/>            | Historical     |
| <input type="checkbox"/>            | Religious      |

Any other (specify) :

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context** : **\* Drawings** (Attach extra sheet if necessary)  
**Urban ✓/ Rural Setting**  
**Surroundings**  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The temple is oriented East/West and faces the East.  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : The pillars and the spandrels of the murkha mdandapa have profuse carvings of stencil patterns, floral and geometrical designs.  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- Structural System** : Indo Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Stone, brick, lime plaster etc.

## 11. Condition Assessment

---

In General

Good<sup>√</sup> / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

The colour of the stone (marble) cladded floor is discoloring. The cornice stone of dirt, dust and stains. This structure racks general mentaince.

---

## 12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**