



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BLW-034

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Peetleshwar Mahadev Mandir  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75°28'E

**LATITUDE** 25°58'N

#### Address

Dhandha Talai Near Love Garden, R.K. Colony Bhilwara

: **Village (village code)**

**Post:** Bhilwara

**District:** Bhilwara

**State:** Rajasthan

**PIN:** 311001

#### Approach district

: The Temple is situated at Dhandha Talai in Jodhpur district. It is 2km away from Jodhpur bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is made on a Raised Platform. In the Sanctum there are several images made of White Marble. This Temple is also related to serpent worship. There are two important images of Hegas in the Shrine.

#### 4. Property Use

---

**ABANDONED /  IN USE**

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 20<sup>th</sup> Century AD  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE / MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** : Living Shrine dedicated to Shiva residing in Palallova.
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

<input type="checkbox"/>	Architectural	
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	: Images of serpent deities.

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context** : \* Drawings (Attach extra sheet if necessary)  
**Urban √/ Rural Setting**  
**Surroundings**  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The temple is Oriented East/West and faces the West.  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : Red Colourd Flag  
Interiors : Foliated arches.  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- Structural System** : Indo Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Marble, Stone, Brick, Lime Plaster

## 11. Condition Assessment

---

In General

Good√ / Fair

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

### In Brief (Attach extra sheet if necessary):

The exterior wall is peeling off due to mainshrine and varied temperature. Also there is Staiwind discoloration of the stone layed for flooring.

---

## 12. Threats to the Property

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input checked="" type="checkbox"/> | Vandalism       |
| <input checked="" type="checkbox"/> | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**