



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BLW-040

SECTION I : IDENTIFICATION

1. Name

Present : Raj Mahal Gateway
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 75° 28' E LATITUDE 25° 58' N

Address : Badnor Kila, Badnor
 : **Village (village code)** Badnor
Post: Badnor **District:** Bhilwara
State: Rajasthan **PIN:** 311301

Approach district : The Gate is situated near by Badnor Kila at Badnor in Bhilwara district. It is 70km away from Bhilwara bus stand. it is well connected by regular bus services.

3. Property Type

<p><i>Buildings</i></p> <input type="checkbox"/> Palace <input type="checkbox"/> Fort <input type="checkbox"/> Citadel <input type="checkbox"/> Govt. building <input type="checkbox"/> Railway station <input type="checkbox"/> Defence building <input type="checkbox"/> Industrial building <input type="checkbox"/> Other public buildings <input type="checkbox"/> Residential building	<p><i>Religious structures</i></p> <input type="checkbox"/> Temple <input type="checkbox"/> Mosque <input type="checkbox"/> Minar <input type="checkbox"/> Church <input type="checkbox"/> Monastery <input type="checkbox"/> Stupa <input type="checkbox"/> Tomb, Mausoleum	<p><i>Other Structures</i></p> <input type="checkbox"/> Wall <input checked="" type="checkbox"/> Gateway <input type="checkbox"/> Pillar <input type="checkbox"/> Others (specify)
<p><i>Engineering structure</i></p> <input type="checkbox"/> Bridge <input type="checkbox"/> Tunnel <input type="checkbox"/> Other engineering structure	<p><i>Open space and related structures</i></p> <input type="checkbox"/> Public square <input type="checkbox"/> Park or garden <input type="checkbox"/> Graveyard <input type="checkbox"/> Baolis, Well	<p>Note: This is an arched based gateway sequented with a sidefall. It has strong roof and has four slender pillars attached to the wall crossing. The main gateway arch flooring with stone slabs.</p>

Tank
 Cave

4. Property Use

ABANDONED√ / IN USE

Present :
Past :

5. Age (Source)

PERIOD : 18th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- WITH EVENTS
 - In History :
 - In Rituals :
 - In Building Construction :
 - Any other (specify) : Large gateway having Nagara Pattern.
- WITH PERSONS
 - Patron :
 - Architect / Engineer :
 - Any other (specify) :

8. Statement of Significance

<input type="checkbox"/>	Architectural	Gateway with boundary wall.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | | |
|--|--|--|
| Context | | * Drawings (Attach extra sheet if necessary) |
| Urban <input checked="" type="checkbox"/> / Rural Setting | | |
| Surroundings | | Stand in Isolation |
| | | Integral part of a Landscape / Street / Complex |

- | | | |
|-------------------------------|----|-----------------------|
| Quantification | | |
| Area Dimension (L x B x H) : | | (m / cm/ feet / inch) |
| Number of Blocks : | 01 | |
| Number of Storys : | 01 | |

- | | | |
|-----------------------------|--|--|
| Spatial Organization | | |
| Orientation : | The gateway is oriented North/South and faces the South. | |
| Plan : | | |
| Allocation of Spaces : | | |

ARCHITECTURAL STYLE

- | | | |
|------------------------------|---|--|
| Ornamentation | | |
| Exteriors : | Arched Gateway with pillars and brackets. | |
| Interiors : | Slender pillar. | |
| Movable Collections : | | |
| Any Other (specify) : | | |

10. Construction Technology

- | | | |
|---------------------------------|--|----------------|
| Structural System | | Indo-Persian |
| Building Techniques | | Arcuate |
| Material of Construction | | Stone, plaster |

11. Condition Assessment

In General

Good[√] / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Broken roof.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS