



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BLW-082

SECTION I : IDENTIFICATION

1. Name

Present : Charbhujia Jee Ka Mandir
Past :
Other Name (if any): :

2. Location

LONGITUDE 75°28'E

LATITUDE 25°58'N

Address

Charbhujia Jee Mandir , Sanganer

: **Village (village code)**

Post: Sanganer

District: Bhilwara

State: Rajasthan

PIN: 311013

Approach district

: The Temple is situated at Sanganer in Bhilwara district. It is 4km away from Bhilwara bus stand. It is well connected by regular bus stand.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: The façade to the temple shrine is painted in bright yellow and has posters of Hindu god and goddesses. Inside the shrine there are numerous posters and boards with arti written on them

4. Property Use

ABANDONED / IN USE ✓

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 11th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify)state Govt.

Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|-------------------------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |

Any other (specify) :

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * Drawings (Attach extra sheet if necessary)
Urban / Rural Setting
Surroundings
Stand in Isolation
Integral part of a Landscape / Street / Complex
- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 01
- **Spatial Organization**
Orientation : The temple is oriented East/West and faces the West.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors :
Interiors : The Mandapa is hexagonal in plan and has printed images of god and goddess on the well.
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Stone, rubble masonry, bricks, lime plasters.

11. Condition Assessment

In General

Good[√] / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The Temple is often crowded and congested and lacks general maintainance.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS