



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BLW-100

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Bawari/Well  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75°28'E

LATITUDE 25°58'N

#### Address

Near, Bada Talab

: **Village (village code)**

**Post:** Sanganer

**District:** Bhilwara

**State:** Rajasthan

**PIN:** 311013

#### Approach district

: The Bawari is situated at Bada talab in Bhilwara district. It is 4km away from Bhilwara bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)  
*Bawari*

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This is a round well with undressed rubble masonry lining. At the ground level near the edge there is two plastered space with two walls to support the pulley demise and serve as railings.

#### 4. Property Use

---

ABANDONED√ / IN USE

Present :  
Past :

#### 5. Age (Source)

---

PERIOD : 18<sup>th</sup> Century AD  
YEARS :

Precise date of Construction :  
Completion :  
Subsequent changes :  
Destruction / Demolition :

#### 6. Ownership / Level of Protection

---

SINGLE / MULTIPLE :

Public : Archaeological Survey of :  
India / State Archaeology :  
Department / Any Other (Please :  
specify)state Govt. :  
Private :  
Any other (Please specify) :  
Name :  
Address :  
Phone :

#### 7. Association

---

- WITH EVENTS
  - In History :
  - In Rituals :
  - In Building Construction :
  - Any other (specify) :
- WITH PERSONS
  - Patron :
  - Architect / Engineer :
  - Any other (specify) :

#### 8. Statement of Significance

---

- |                                     |                |
|-------------------------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural  |
| <input type="checkbox"/>            | Archaeological |
| <input type="checkbox"/>            | Historical     |
| <input type="checkbox"/>            | Religious      |

Any other (specify) :

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context** : **\* Drawings** (Attach extra sheet if necessary)  
**Urban ✓/ Rural Setting**  
**Surroundings**  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks :  
Number of Storys :  
  
- **Spatial Organization**  
Orientation : The bawari is oriented East/West and faces the West.  
Q :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors :  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- Structural System** :
- Building Techniques** : Undress rubble masonry
- Material of Construction** : Stone.

## 11. Condition Assessment

---

In General

Good / Fair

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/>            | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

### In Brief (Attach extra sheet if necessary):

Stone slabs and rubble is fragmenting and falling apart. Also there is vegetational growth in four around the well.

---

## 12. Threats to the Property

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input checked="" type="checkbox"/> | Vandalism       |
| <input checked="" type="checkbox"/> | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**