



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-105

SECTION I : IDENTIFICATION

1. Name

Present : Well
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 75°28'E

LATITUDE 25°58'N

Address

Near, Badnor Kila

: **Village (village code)**

Post: Badnor

District: Bhilwara

State: Rajasthan

PIN: 311001

Approach district

: The Well is situated near Badnor Kila at Badnor in Bhilwara district. It is 70km away from Bhilwara. it is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: The well is square in shape. It is clad with lime-plaster. The well is not functional.

4. Property Use

ABANDONED√ / IN USE

Present :
Past :

5. Age (Source)

PERIOD : 18th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- WITH EVENTS
 - In History :
 - In Rituals :
 - In Building Construction :
 - Any other (specify) :
- WITH PERSONS
 - Patron :
 - Architect / Engineer :
 - Any other (specify) :

8. Statement of Significance

- | | |
|-------------------------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |

Any other (specify) :

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : *** Drawings** (Attach extra sheet if necessary)
Urban ✓/ Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks :
Number of Storys :

• **Spatial Organization**
Orientation : The well is oriented East/West and faces the East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Well is cladded with lime-plaster.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Well cladded with rubble masonry
- Building Techniques** :
- Material of Construction** : Rubble masonry and plaster.

11. Condition Assessment

In General

Good√ / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Badly damaged

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS