



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-107

SECTION I : IDENTIFICATION

1. Name

Present : Well
Past :
Other Name (if any): :

2. Location

LONGITUDE 75°28'E

LATITUDE 25°58'N

Address

Bajrang Wayamshala , Teja Jee Sthal Sanganer

: **Village (village code)**

Post: Sanganer

District: Bhilwara

State: Rajasthan

PIN: 311013

Approach district

: The Well is situated near by Teja Jee Chhatri at Sanganer in Bhilwara district. It is 4km away from Bhilwara bus stand. it is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|-------------------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input checked="" type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: Lined with rubble masonry , this well seems to be quite deep and still functional. Along the edge there is a projecting stone slab with a hole in it, probably to support the pully. In the same vicinity there is a stone sculptured Nandi figure seated on a pila of stone.

4. Property Use

ABANDONED√ / IN USE

Present :
Past :

5. Age (Source)

PERIOD : 19th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology :
Department / Any Other (Please :
specify)state Govt. :
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- WITH EVENTS
 - In History :
 - In Rituals :
 - In Building Construction :
 - Any other (specify) :
- WITH PERSONS
 - Patron :
 - Architect / Engineer :
 - Any other (specify) :

8. Statement of Significance

| | |
|-------------------------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |

- | | | |
|--------------------------|---------------------|---|
| <input type="checkbox"/> | Religious | : |
| <input type="checkbox"/> | Any other (specify) | : |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : *** Drawings** (Attach extra sheet if necessary)
- Urban / Rural Setting**
- Surroundings**
- Stand in Isolation**
- Integral part of a Landscape / Street / Complex**

- **Quantification**
- Area Dimension (L x B x H) : (m / cm/ feet / inch)
- Number of Blocks :
- Number of Storys :

- **Spatial Organization**
- Orientation : The well is oriented East/West and faces the East.
- Plan :
- Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
- Exteriors : Plain and no ornamentation
- Interiors :
- Movable Collections :
- Any Other** (specify) :

10. Construction Technology

- Structural System** : Indo Persian
- Building Techniques** : Corbelled
- Material of Construction** : Partially dressed rubble masonry.

11. Condition Assessment

In General

Good√ / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Excessive accumulation of dirt dust and other pollutants on the stone slabs and bolders that comprise the well wall. The stone slabs used on the edges are breaking off and chipping .

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS