



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-127

SECTION I : IDENTIFICATION

1. Name

Present : Kamabar Singh Ki Chhatri
Past :
Other Name (if any): :

2. Location

LONGITUDE 75°28'E

LATITUDE 25°58'N

Address

Chhatri Ghat, Kamal Talab, Hameergarh

: **Village (village code)**
Hameergarh
Post: Hameergarh **District:** Bhilwara
State: Rajasthan **PIN:** 311025

Approach district : The Chhatri is situated near by Kamal Talab, at Hameergarh in Bhilwara district. It is 20km away from Bhilwara district. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)
Chhatri

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: This Chhatri is raised on a high platform and is hexagonal in plan. It has domical roofing with lotus panel along the rim of the drum. Inside the Chhatri there are two free standing stone slabs with carved figures over it. The Chhatri has foliated arched openings

4. Property Use

ABANDONED√ / IN USE

Present : Memorial
Past : Memorial

5. Age (Source)

PERIOD : 19th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural
<input type="checkbox"/>	Archaeological
<input type="checkbox"/>	Historical

<input type="checkbox"/>	Religious	:
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | | |
|--|--|--|
| Context | | * Drawings (Attach extra sheet if necessary) |
| Urban <input checked="" type="checkbox"/> Rural <input type="checkbox"/> Setting | | |
| Surroundings | | |
| | | Stand in Isolation |
| | | Integral part of a Landscape / Street / Complex |

- | | | |
|------------------------------|---|-----------------------|
| Quantification | | |
| Area Dimension (L x B x H) | : | (m / cm/ feet / inch) |
| Number of Blocks | : | 01 |
| Number of Storys | : | 01 |

- | | | |
|-----------------------------|---|---|
| Spatial Organization | | |
| Orientation | : | The chhatri is oriented East/West and faces the East. |
| Plan | : | |
| Allocation of Spaces | : | |

ARCHITECTURAL STYLE

- | | | |
|----------------------------|---|---|
| Ornamentation | | |
| Exteriors | : | The Façade of the arch is profusely carved it over the coiling there are some reminents of paintings in blue and red. |
| Interiors | : | |
| Movable Collections | : | |
| Any Other (specify) | : | |

10. Construction Technology

- | | | |
|---------------------------------|---|-----------------------|
| Structural System | : | Indo Persian |
| Building Techniques | : | Arcuate |
| Material of Construction | : | Stone, rubble masonry |

11. Condition Assessment

In General

Good√ / Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

The painted layer is coming off along the lime plaster. Also there is discolouration and staining along the structure.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input checked="" type="checkbox"/> | Vandalism |
| <input checked="" type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS