



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-132

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Chhitauri Gate  
**Past** :  
**Other Name (if any):** : Chittauri Darwaja

#### 2. Location

**LONGITUDE** 75°28'E

**LATITUDE** 25°58'N

#### Address

Chittaur Darwaja, Hameergarh

: **Village (village code)** Hameergarh

**Post:** Hameergarh

**District:** Bhilwara

**State:** Rajasthan

**PIN:** 311025

**Approach district** : The Darwaja is situated near Kamal Talab at Hameergarh in Bhilwara district. It is 20km away from Bhilwara bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- |                          |                        |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace                 |
| <input type="checkbox"/> | Fort                   |
| <input type="checkbox"/> | Citadel                |
| <input type="checkbox"/> | Govt. building         |
| <input type="checkbox"/> | Railway station        |
| <input type="checkbox"/> | Defence building       |
| <input type="checkbox"/> | Industrial building    |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building   |

##### *Religious structures*

- |                          |                 |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple          |
| <input type="checkbox"/> | Mosque          |
| <input type="checkbox"/> | Minar           |
| <input type="checkbox"/> | Church          |
| <input type="checkbox"/> | Monastery       |
| <input type="checkbox"/> | Stupa           |
| <input type="checkbox"/> | Tomb, Mausoleum |

##### *Other Structures*

- |                                     |                  |
|-------------------------------------|------------------|
| <input type="checkbox"/>            | Wall             |
| <input checked="" type="checkbox"/> | Gateway          |
| <input type="checkbox"/>            | Pillar           |
| <input type="checkbox"/>            | Others (specify) |

##### *Engineering structure*

- |                          |                             |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge                      |
| <input type="checkbox"/> | Tunnel                      |
| <input type="checkbox"/> | Other engineering structure |

##### *Open space and related structures*

- |                          |                |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square  |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard      |
| <input type="checkbox"/> | Baolis, Well   |
| <input type="checkbox"/> | Tank           |
| <input type="checkbox"/> | Cave           |

**Note:** This is a massive and a lofty pointed arched gateway.

#### 4. Property Use

---

ABANDONED / IN USE ✓

Present :  
Past :

#### 5. Age (Source)

---

PERIOD : 18<sup>th</sup> Century AD  
YEARS :

Precise date of Construction :  
Completion :  
Subsequent changes :  
Destruction / Demolition :

#### 6. Ownership / Level of Protection

---

SINGLE / MULTIPLE :

Public : Archaeological Survey of :  
India / State Archaeology :  
Department / Any Other (Please :  
specify)state Govt. :  
Private :  
Any other (Please specify) :  
Name :  
Address :  
Phone :

#### 7. Association

---

- WITH EVENTS
  - In History :
  - In Rituals :
  - In Building Construction :
  - Any other (specify) :
- WITH PERSONS
  - Patron :
  - Architect / Engineer :
  - Any other (specify) :

#### 8. Statement of Significance

---

<input checked="" type="checkbox"/>	Architectural
<input type="checkbox"/>	Archaeological
<input type="checkbox"/>	Historical

<input type="checkbox"/>	Religious	:
<input type="checkbox"/>	Any other (specify)	:

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- |   |  |  |
|---|--|--|
| <b>Context</b>  |  | <b>* Drawings</b> (Attach extra sheet if necessary)    |
| Urban <input checked="" type="checkbox"/> / Rural Setting |  |  |
| Surroundings  |  |  |
|   |  | <b>Stand in Isolation</b>                              |
|   |  | <b>Integral part of a Landscape / Street / Complex</b> |
  
- |                              |   |                       |
|------------------------------|---|-----------------------|
| <b>Quantification</b>        |   |                       |
| Area Dimension ( L x B x H ) | : | (m / cm/ feet / inch) |
| Number of Blocks             | : |                       |
| Number of Storys             | : |                       |
  
- |                             |   |  |
|-----------------------------|---|--|
| <b>Spatial Organization</b> |   |  |
| Orientation                 | : | The dawaja is oriented East/West and faces the East. |
| Plan                        | : |  |
| Allocation of Spaces        | : |  |

### **ARCHITECTURAL STYLE**

- |                            |   |   |
|----------------------------|---|---|
| <b>Ornamentation</b>       |   |   |
| Exteriors                  | : | The façade is pointed in outer red and the reliefs in yellow. |
| Interiors                  | : |   |
| Movable Collections        | : |   |
| <b>Any Other</b> (specify) | : |   |

### **10. Construction Technology**

---

- |                                 |   |                                     |
|---------------------------------|---|-------------------------------------|
| <b>Structural System</b>        |   | Indo Persian                        |
| <b>Building Techniques</b>      | : | Arcuate system                      |
| <b>Material of Construction</b> | : | Stone, rubble masonry lime plaster. |

## 11. Condition Assessment

---

In General

Good√ / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

The coloured tiles have fallen off and have been replaced by soot other pollutant. There is general degeneration of plaster and painted layer. This structure lacks general mentaince. Also it is burdurned with urban pressure.

---

## 12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**