



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-146

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Chhatri  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75°28'E

LATITUDE 25°58'N

#### Address

Akshay Sagar, Badnor

: **Village (village code)**

**Post:** Badnor

**District:** Bhilwara

**State:** Rajasthan

**PIN:** 311301

#### Approach district

: The Chhatri is situated near by Akshay Sagar at Badnor in Bhilwara district. It is 70km away from Bhilwara bus stand. it is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)  
*Chhatri*

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a canopied Chhatri. The pinnacle of the Chhatri is missing. The Chhatri stands on a raised platform. Dome is damaged.

#### 4. Property Use

---

ABANDONED<sup>√</sup> / IN USE

Present : Memorial  
Past : Memorial

#### 5. Age (Source)

---

PERIOD : 19<sup>th</sup> Century AD  
YEARS :

Precise date of Construction :  
Completion :  
Subsequent changes :  
Destruction / Demolition :

#### 6. Ownership / Level of Protection

---

SINGLE / MULTIPLE :

Public : Archaeological Survey of :  
India / State Archaeology  
Department / Any Other (Please  
specify)state Govt.  
Private :  
Any other (Please specify) :  
Name :  
Address :  
Phone :

#### 7. Association

---

- WITH EVENTS
  - In History :
  - In Rituals :
  - In Building Construction :
  - Any other (specify) :
- WITH PERSONS
  - Patron :
  - Architect / Engineer :
  - Any other (specify) :

#### 8. Statement of Significance

---

<input checked="" type="checkbox"/>	Architectural	Dome has decorative pattern.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	

<input type="checkbox"/>	Religious	:
<input type="checkbox"/>	Any other (specify)	:

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- |  |  |  |
|--|--|--|
| <b>Context</b>   |  | * <b>Drawings</b> (Attach extra sheet if necessary)    |
| Urban <input checked="" type="checkbox"/> / Rural <input type="checkbox"/> Setting |  |  |
| Surroundings   |  |  |
|  |  | <b>Stand in Isolation</b>                              |
|  |  | <b>Integral part of a Landscape / Street / Complex</b> |
  
- |                              |   |                       |
|------------------------------|---|-----------------------|
| <b>Quantification</b>        |   |                       |
| Area Dimension ( L x B x H ) | : | (m / cm/ feet / inch) |
| Number of Blocks             | : | 01                    |
| Number of Storys             | : | 01                    |
  
- |                             |   |   |
|-----------------------------|---|---|
| <b>Spatial Organization</b> |   |   |
| Orientation                 | : | The Chhatri is oriented North/South and faces the South |
| Plan                        | : |   |
| Allocation of Spaces        | : |   |

### **ARCHITECTURAL STYLE**

- |                            |   |
|----------------------------|---|
| <b>Ornamentation</b>       |   |
| Exteriors                  | : |
| Interiors                  | : |
| Movable Collections        | : |
| <b>Any Other</b> (specify) | : |

### **10. Construction Technology**

---

<b>Structural System</b>	:	Indo Persian
<b>Building Techniques</b>	:	Arcuate system
<b>Material of Construction</b>	:	Stone

## 11. Condition Assessment

---

In General

Good√ / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Dome is mutilated, mutilated 'Shivalinga' discolouration deposition of sooth.

---

## 12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**