



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/BLW-150

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Bangsola Mahadev Mandir  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75°28'E

**LATITUDE** 25°58'N

#### Address

Bangsola Menhaden Mandir, Hameergarh

: **Village (village code)**

**Post:** Hameergarh

**District:** Bhilwara

**State:** Rajasthan

**PIN:** 311025

#### Approach district

: The Temple is situated at Hameergarh in Bhilwara district. It is 20km away from Bhilwara bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This is a small inconspicuous shrine with thick walls and narrow doors. Inside the sanctum there is a shivling along with his conon and other deities. The roof is a small dome. The ceiling of the mandapa is a colorful Masonic of blue and silver foil and glass work,

#### 4. Property Use

---

ABANDONED√ / IN USE

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 19<sup>th</sup> Century AD  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

SINGLE / MULTIPLE :

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)state Govt.

**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                |
|-------------------------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural  |
| <input type="checkbox"/>            | Archaeological |
| <input type="checkbox"/>            | Historical     |
| <input type="checkbox"/>            | Religious      |

Any other (specify) :

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context** : **\* Drawings** (Attach extra sheet if necessary)  
**Urban** ✓ / **Rural Setting**  
**Surroundings**  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 01
- **Spatial Organization**  
Orientation : The temple is oriented East/West and faces the East.  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : Plain and simple  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- Structural System** : Indo Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Stone, rubble, lime, metal etc.

## 11. Condition Assessment

---

In General

Good√ / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

The exterior wall has developed cracks which are causing flaking. There is blackening and soot deposit and the stains. The sanctum is quite ill kept. There is excessive moisture in it on the floor and the walls.

---

## 12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**