

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No: RJ/BSW-007 **SECTION I: IDENTIFICATION** 1. Name Present Shiv Jee Ka Mandir **Past** Other Name (if any): 2. Location **LONGITUDE** 74°47'E LATITUDE 23°35'N Address Near Chhatri Bai Talab road, Banswara Village (village code) Post: Banswara **District:** Banswara State: Rajasthan **PIN:** 327001 **Approach district** The Temple is situated at Banswara. It is 2km away from Banswara bus stand. It is well connected by regular bus services. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is an old temple in a structures ruined state. 'Shikhara' of the Bridge Public square temple is crowned by 'Amalaka'. Stone image of 'Nandi' Tunnel Park or garden Graveyard is facing towards deities. Other engineering structure Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE $\sqrt{}$
Present Past	:	Religious Religious
5. Age (Source)		
PERIOD YEARS	:	19 th Century AD
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : :	
6. Ownership / Level of Protection	<u>on</u>	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.	:	
Private Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction Any other (specify)	:	
WITH PERSONS	•	
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
√ Architectural Archaeological		
Historical		
Religious		

	Any other (specify)	:				
SECTION II: DESCRIPTION						
9.	Physical Description and De	cor	ative Features			
•	Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)			
			Stand in Isolation Integral part of a Landscape / Street / Complex			
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)			
	Number of Blocks Number of Storys	:	01 01			
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Temple is oriented East/West and faces the West.			
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections By Other (specify)	: : : : : : : : : : : : : : : : : : : :	Stone image of 'Nandi'			

10. Construction Technology

Structural System Building Techniques Material of Construction Nagara style of temple Arcuate system Stone

11. Condition Assessme	ent
In General	Good√ / Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sh	eet if necessary):
Algae formation, deposit	ion of sooth, blackening etc.
12. Threats to the Prope	erty
	√ NaturalNegligenceVandalismUrban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS