

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No: RJ/BSW-013 **SECTION I: IDENTIFICATION** 1. Name Present Bai Talab **Past** Other Name (if any): 2. Location **LONGITUDE** 74°47'E LATITUDE 23°35'N Address Bai Talab, Banswara Village (village code) Post: Banswara **District:** Banswara State: Rajasthan **PIN:** 327001 **Approach district** The Talab is situated at Banswara district. It is 4km away from Banswara bus stand. it is well connected by regular bus services. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Others (specify) Govt. building Church Railway station Monastery Talab Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a large pond full of structures water. There is an old Masonic structure at one end of the pond. Bridge Public square The pond can be approached by Tunnel Park or garden Graveyard means of staircases which are in a Other engineering structure bad condition. Baolis, Well Tank

Cave

	Any other (specify)	:		
SECTION II: DESCRIPTION 9. Physical Description and Decorative Features				
•	Context Urban √ Rural Setting Surroundings	<u></u>	* Drawings (Attach extra sheet if necessary) Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (LxBxH) Number of Blocks Number of Storys	:	(m / cm/ feet / inch)	
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The Talab is oriented East/West and faces the West.	
•	Ornamentation Exteriors Interiors Movable Collections ny Other (specify)	: : : : : : : : : : : : : : : : : : : :		
10	. Construction Technology			
	Structural System Building Techniques Material of Construction	: : :	Pond having scenic landscape.	

11. Condition Assessment	
In General	Good√ / Fair
In Brief (Attach extra shee necessary):	Sign of Deterioration Serious Deterioration Danger of Disappearance
It has not been maintained pro	pperly.
	√ NaturalNegligenceVandalismUrban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS