

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BSW-096 **SECTION I: IDENTIFICATION** 1. Name Present Shiv Mandir Ka Khandar **Past** Other Name (if any): 2. Location **LONGITUDE** 74°47'E LATITUDE 23°35'N Address Nilkanth Mahadev Group Arthwna Village (village code) Arthwna Post: Arthwna **District:** Banswara State: Rajasthan **PIN:** 327801 Approach district The temple is situated at Arthwna in Banswara district. It is 60km away from Banswara bus stand. It is well connected by regular bus services. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related **Note:** This temple is made upon structures an elevated Platform with upraised staircases. It has Pyramidal Bridge Public square Tunnel Park or garden Superstructure. Sanctum Graveyard Sanctorum enshrines Lingam. Other engineering structure Baolis, Well Tank Cave

4. Property Use		
	ABANDONED√ / IN USE	
Present Past	: Religious	
5. Age (Source)		
PERIOD YEARS	: 11 th Century AD :	
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : :	
6. Ownership / Level of Protection		
	SINGLE /MULTIPLE :	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone 7. Association	: : : :	
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	: : : : : : : Temple	
√ ArchitecturalArchaeologicalHistoricalReligious	Pyramidal Superstructure	

Any other (specify)	:	
SECTION II: DESCRIPTION		
9. Physical Description and Decorative Features		
 Context Urban √ Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary)	
C	Stand in Isolation Integral part of a Landscape / Street / Complex	
Quantification Area Dimension (L x B x H)	: (m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	
 Spatial Organization Orientation Plan Allocation of Spaces 	: The temple is Oriented East/West and faces the East. :	
 ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Any Other (specify) 	: Pyramidal superstructure. :	
10. Construction Technology		

Structural System: Indo PersianBuilding Techniques: Arcuate systemMaterial of Construction: Stone and plaster etc.

11. Condition Assessment	
In General	Good / Fair $\sqrt{}$
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet	if necessary):
Blackening of Surface.	
12. Threats to the Property	
	√ Natural
	Negligence Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS