

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BSW-110

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Shiv Mandir : :	
LONGITUDE 74°47'E	LATITUDE 23°35'N	
Address	Nilkanth Mahadev Group A	rthwna
	: Village (village code)	Arthwna
Approach district 3. Property Type		District: Banswara PIN: 327801 at Arhwna in Banswara district. Banswara bus stand. It is well s services.
Buildings	Religious structures	Other Structures
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	√ Temple Mosque	Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures etc. Public square structures Park or garden v Graveyard structures	Note: This temple is made upon elevated platform with upraised staircases. It has well decorated valls with figures. The Superstructure of the temple had been fallen down.

4. Property Use

_

		ABANDONED√ / IN USE
Present Past	:	Religious
5. Age (Source)		
PERIOD YEARS	:	11 th Century AD
Precise date of Construction Completion Subsequent changes Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey ofIndia / State ArchaeologyDepartment / Any Other (Pleasespecify)state Govt.PrivateAny other (Please specify)NameAddressPhone7. Association	:	A.S.I
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS	: : : : : : : : : : : : : : : : : : : :	Temple

 Architectural	
Archaeological	Walls with decorated figures
Historical	

Religious
Any other (specify)

SECTION II: DESCRIPTION

:

9. Physical Description and Decorative Features

•	Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
	Ū		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The temple is oriented East/West and faces the West.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)	:	Walls with decorated with female figures

10. Construction Technology

Structural System	:	Indo Persian
Building Techniques	:	Arcuate system
Material of Construction	:	Stone and plaster etc.

11. Condition Assessment

In General

Good / Fair $\sqrt{}$

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Breaking of Structure 12. Threats to the Property

 Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attach list as in page C in some of multiple photographe)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS