



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BSW-128

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Ganesh jee ka Mandir  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 74° 47' E

**LATITUDE** 23° 35' N

**Address**

Nilkanth Mahadev Group Arthuna

: **Village (village code)** Arthuna  
**Post** : Arthuna **District:** Banswara  
**State** : Rajasthan **PIN:** 327801

**Approach**

: The Mandir is situated at Arthuna. It is 60 k.m. away from Banswara bus stand. It is well connected by regular bus services.

#### 3. Property Type

**Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

**Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

**Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

**Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

**Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It has pyramidal superstructure. It enshrines Lord Ganesha in it.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 11<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology : Archaeological Survey of India  
Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** : Temple
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                          |
|-------------------------------------|---------------------|--------------------------|
| <input checked="" type="checkbox"/> | Architectural       | Pyramidal superstructure |
| <input type="checkbox"/>            | Archaeological      |                          |
| <input type="checkbox"/>            | Historical          |                          |
| <input type="checkbox"/>            | Religious           |                          |
| <input type="checkbox"/>            | Any other (specify) |                          |



## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**