

Past

#### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

### **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: RJ/BSW-129 **SECTION I: IDENTIFICATION** 1. Name Present Jain Mandir – 2 Other Name (if any): 2. Location 23<sup>0</sup> 35<sup>'</sup> N LONGITUDE 74° 47' E LATITUDE **Address** Nilkanth Mahadev, Arthuna Village (village code) Arthuna Post: Arthuna District: Banswara State: Rajasthan **PIN:** 327801 Approach The Mandir is situated at Arthuna. It is 60 k.m. away from Banswara bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The temple is in ruins. It structures broken has curvilinear Public square superstructure. It has well Bridge managed staircases. Tunnel Park or garden Graveyard Other engineering structure Baolis, Well

Tank Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present Past	: : Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: 11 <sup>th</sup> Century A.D. :
6. Ownership / Level of Protection	
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Archaeological Survey of India
Private	:
Any other (Please specify) Name	: :
Address	:
Phone	:
7. Association	
<ul> <li>WITH EVENTS         <ul> <li>In History</li> <li>In Rituals</li> <li>In Building Construction</li> <li>Any other (specify)</li> </ul> </li> <li>WITH PERSONS         <ul> <li>Patron</li> <li>Architect / Engineer</li> <li>Any other (specify)</li> </ul> </li> </ul>	: Temple : : :
8. Statement of Significance	
<ul> <li>✓ Architectural</li> <li>Archaeological</li> <li>Historical</li> <li>Religious</li> <li>Any other (specify)</li> </ul>	Damaged Curvilinear spire

# SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features				
Context     Urban / Rural Setting     Surroundings			* <b>Drawings</b> (Attach extra sheet if necessary) Urban		
			Stand in Isolation Integral part of a Landscape / Street / Complex		
•	<b>Quantification</b> Area Dimension ( L x B x H	H) :	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	01 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Mandir is oriented North/South and faces the North		
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :	Curvilinear spire		
10.	Construction Technology	у			
	Structural System Building Techniques Material of Construction	: : :	Nagar style of temple Trabeate Bricks & Stone		
11.	Condition Assessment				
	In General	Good A	/ Fair		
	Sign of Deterioration Serious Deterioration Danger of Disappearance	e			
In l	Brief (Attach extra sheet i	f neces	ssary):		
Ва	dly damaged				

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

## SECTION III: REFERENCES

### 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS