



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-133

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Mandir Shree Sanwalia jee Maharaj  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 76° 19' E

**LATITUDE** 25° 53' N

#### Address

Lanka Gate Road, Bundi

: **Village (village code)**

**Post** : Bundi

**District**: Bundi

**State** : Rajasthan

**PIN**: 323001

#### Approach

: The Temple is situated at Bundi City. It is 2 k.m. away from Bundi bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is made on an elevated platform. It has raised staircases. It has curvilinear spire. It has kangura pattern. The pillars with brackets giving support to the superstructure. It has multiple bhoonies.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 19<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)

**Private** : Bagari Samaj Navyuvak Mandal (Utthan Samaj), Bundi (Rajasthan)

**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** : Temple
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                          |
|-------------------------------------|---------------------|--------------------------|
| <input checked="" type="checkbox"/> | Architectural       | It has curvilinear spire |
| <input type="checkbox"/>            | Archaeological      |                          |
| <input type="checkbox"/>            | Historical          |                          |
| <input type="checkbox"/>            | Religious           |                          |
| <input type="checkbox"/>            | Any other (specify) |                          |



## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

##### **NAME**

##### **NAME**

#### **18. Reviewers**

##### **NAME**

##### **NAME**

##### **COMMENTS**

##### **COMMENTS**