

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-136

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Dhabhai ka Kund : :	
LONGITUDE 76 ⁰ 19 [°] E	LATITUDE 25° 53' N	
Address	Lanka Gate Road, Bundi	
	: Village (village code) Post : Bundi District: Bundi State : Rajasthan PIN: 323001	
Approach	: The Kund is situated at Bundi City. It is 2 k.m. away from Bundi bus stand. It is well connected by regular bus services.	

3. Property Type

Buildings	Religious structures	Other Structures
Palace	Temple	Wall
Fort	Mosque	Gateway
Citadel	Minar	Pillar
Govt. building	Church	✓ Others (specify)
Railway station	Monastery	Kund
Defence building	Stupa	
Industrial building	Tomb, Mausoleum	
Other public buildings		
Residential building		
Engineering structure	Open space and related structures	Note: The kund is a deep artificial water reservoir. It is within a well
Bridge	Public square	elevated platform and within a
Tunnel	Park or garden	fortified wall. It has multiple
Other engineering structur	e Graveyard	staircases.
	Baolis, Well	
	Tank	
	Cave	

4. Property Use

	ABANDONED / IN USE : Abandoned
Present	:
Past	:
5. Age (Source)	
PERIOD	: 18 th Century A.D.
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	: State Archaeology Department
India / State Archaeology	<i>.</i>
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	: Kund
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
✓ Architectural	Water reservoir (artificial)
Archaeological	
Historical	
Religious	
Any other (specify)	

SECTION II: DESCRIPTION

9.	Physical Description and De	cor	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch)
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Kund is oriented East/West and faces the West
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : :	Staircases Foot prints impression

10. Construction Technology

Structural System Building Techniques Material of Construction		Hydraulic system Trabeate Sandstone
--	--	---

11. Condition Assessment

In General	Good / Fair Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS