

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-192 **SECTION I: IDENTIFICATION** 1. Name Present Khatikwala gate Past Other Name (if any): 2. Location LONGITUDE 76° 19' E 25⁰ 53['] N LATITUDE **Address** Bundi City Village (village code) Post: Bundi District: Bundi State: Rajasthan **PIN:** 323001 Approach The Gateway is situated ad Bundi City. It is 1 k.m. away from Bundi Bus Stand. It is well connected by regular bus services 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Open space and related Engineering structure Note: This is a large massive structures gateway of Khatikwala. It has foliated arch opening and spandrel Bridge Public square Tunnel Park or garden is decorated with medallion. Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present Past	: Gateway
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: 17 th Century A.D. : : :
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	: : : : :
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: Gateway : : :
8. Statement of Significance	
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	It has foliated arch entrance

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban		
			Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x F	H) :	(m. / am/fact / in ah)		
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01		
•	Spatial Organization Orientation	:	The Gateway is oriented North-South and faced the		
	Plan Allocation of Spaces	:	North		
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : :	Foliated arch, spandrel with medallion		
10	. Construction Technology	y			
	Structural System Building Techniques Material of Construction	: :	Indo-Persian Trabeate & Arcuate Bricks and Stone		
11	. Condition Assessment				
	In General	Good Good	/ Fair		
	Sign of Deterioration Serious Deterioration Danger of Disappearance)			
In	Brief (Attach extra sheet it	f neces	ssary):		
Da	mpness, plaster peeling off,	Blacke	ening of surface		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS