

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-206

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	: Nasiya jee ki Baoli :
2. Location	
LONGITUDE 76° 19 [°] E	LATITUDE 25° 53' N
Address	Kashar Bagh Road, Bundi
Approach	 Village (village code) Post : Bundi District: Bundi State : Rajasthan PIN: 323001 The Baoli is situated at Bundi City. It is 3 km. away from Bundi bus stand. It is well connected by regular
	bus services.

3. Property Type

of Nasiya
reservoir
shaped. It
ular arch.
ted with
managed
ee falling
r s t

4. Property Use

	ABANDONED / IN USE : Abandoned
Present Past	:
5. Age (Source)	
PERIOD	: 18 th Century A.D.
YEARS	
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	ion
	SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please	:
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address Phone	
Thone	•
7. Association	
WITH EVENTS	
In History	: Baoli
In Rituals	
In Building Construction Any other (specify)	
WITH PERSONS	•
Patron	:
Architect / Engineer	
Any other (specify)	:
8. Statement of Significance	
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	It is a rectangular shaped water reservoir

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Baoli is oriented East-West and faces the West	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Foliated arch, staircases, chajja	

10. Construction Technology

Structural System Building Techniques Material of Construction		Hydraulic system Rectangular shaped water reservoir Bricks and stone
--	--	--

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Algae formation, Dust and dirt deposition.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS