


INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-220

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any):	: Dalel Singh ki Chhatri :		
2. Location			
LONGITUDE 76 ⁰ 19 ['] E	LATITUDE 25° 53' N		
Address	Kashar Bagh, Bundi		
	: Village (village code) Post : Bundi District: Bundi State : Rajasthan PIN: 323001		
Approach	: The Chhatri is situated at Bundi City. It is 4 km. away from Bundi bus stand. It is well connected by regular bus services.		
3. Property Type			



4. Property Use

	ABANDONED / IN USE : Abandoned	
Present Past	: Memorial :	
5. Age (Source)		
PERIOD	: 18 th Century A.D.	
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
	SINGLE /MULTIPLE :	
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name		
Address		
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction		
Any other (specify)	: Memorial	
WITH PERSONS		
Patron		
Architect / Engineer Any other (specify)		
Any other (specify)		
8. Statement of Significance		
Architectural	Canopied chhatri	
Archaeological	ouropiou ornaur	

Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation	
			Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:		
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Chhatri is oriented North/South and faces the South	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Canopied chhatri	

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of wall, plaster peeling off, dust and dirt deposition.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS