



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-267

SECTION I : IDENTIFICATION

1. Name

Present : Dha Bhai Bhawan
Past :
Other Name (if any): :

2. Location

LONGITUDE 76° 19' E

LATITUDE 25° 53' N

Address

Banganga Shikar Buraj, Bundi

: **Village (village code)**

Post : Bundi

District: Bundi

State : Rajasthan

PIN: 323001

Approach

: The Bhawan is situated at Banganga in Bundi district. It is 5 km. away from Bundi. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)
Bhawan

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: This is a Bhawan of Dha Bhai. It has well managed staircases. It has flat roof and boundary of roof is surmounted by kangura pattern. It has free falling chajja and foliated arches.

4. Property Use

ABANDONED / IN USE : In use

Present :
Past : Bhawan

5. Age (Source)

PERIOD : 17th Century A.D.
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** : Residential building
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input type="checkbox"/>	Architectural	It has kangura pattern design on the wall
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings
*** Drawings** (Attach extra sheet if necessary)
Rural setting
Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 01

- **Spatial Organization**
Orientation : The Bhwan is oriented North-South and faces the North
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Chajja, kangura pattern, foliated arch
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone and bricks

11. Condition Assessment

In General	Good / Fair
	Good

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface, plaster peeling off, dust and dirt deposition.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS