

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-298

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any):	: Sas Bahu Kund :
2. Location	
LONGITUDE 76 ⁰ 19 ['] E	LATITUDE 25 ⁰ 53 ['] N
Address	Sathur, Bundi
Approach	 Village (village code) Post : Sathur District: Bundi State : Rajasthan PIN: 323001 The Tank is situated at Sathur in Bundi District. It is 10 km. away from Bundi. It is well connected by regular bus services.
3. Property Type	
Buildings	Religious structures Other Structures
Palace	
Fort	Mosque Gateway
Citadel	Minar Pillar
Govt. building	Church Others (specify)
Railway station	Monastery
Defence building	Stupa
Industrial building	Tomb, Mausoleum

Engineering structure

Other engineering structure

Bridge

Tunnel

Other public buildings Residential building



Graveyard

Baolis, Well Tank Cave **Note:** This is a small and closed water reservoir. It is surrounded by boundary wall of the water reservoir has alcoves in it. It has painted arch and spandrel is decorated with medallion.

4. Property Use

		ABANDONED / IN USE : Abandoned
Present	:	Poligious
Past	•	Religious
5. Age (Source)		
PERIOD	:	18 th Century A.D.
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	÷	
Destruction / Demolition	•	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify) Private		
Any other (Please specify)	:	
Name		
Address	÷	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	Kund
In Rituals	:	
In Building Construction	÷	
Any other (specify) WITH PERSONS 	÷	
• WITH PERSONS Patron		
Architect / Engineer	:	
Any other (specify)	÷	
	•	
8. Statement of Significance		
Architectural	lt is	s surrounded by boundary wall
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation	
			Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch)	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Tank is oriented East-West and faces the East	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : :	Pointed arch, boundary wall	

10. Construction Technology

Structural System Building Techniques	:	Indo-Persian Arcuate system
Material of Construction		Bricks & Stone

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Algae formation, vegetation growth, Dust and Dirt Deposition

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS