

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-300

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Bhuteshwar Mahadev Mandir :
LONGITUDE 76 ⁰ 19 ['] E	LATITUDE 25 ⁰ 53 ['] N
Address	Sathur, Bundi
	: Village (village code) Post : Sathur District: Bundi State : Rajasthan PIN: 323001
Approach	: The Temple is situated at Sathur in Bundi District. It is 10 km. away from Bundi. It is well connected by regular bus services.

3. Property Type

 Buildings		Religious structures	Other Structures
Palace	>	Temple	Wall
Fort		Mosque	Gateway
Citadel		Minar	Pillar
Govt. building		Church	Others (specify)
Railway station		Monastery	
Defence building		Stupa	
Industrial building		Tomb, Mausoleum	
Other public buildings			
Residential building			
Engineering structure	-	oen space and related ructures	Note: This temple is Nagar style of temple and is dedicated to
 Engineering structure	-		
	-	ructures	of temple and is dedicated to
Bridge	-	r uctures Public square	of temple and is dedicated to Shiva. It has curvilinear superstructure. Porch of the temple has domical chhatri. Drum
Bridge Tunnel	-	r uctures Public square Park or garden	of temple and is dedicated to Shiva. It has curvilinear superstructure. Porch of the temple has domical chhatri. Drum of the temple is dedicated to
Bridge Tunnel	-	r uctures Public square Park or garden Graveyard	of temple and is dedicated to Shiva. It has curvilinear superstructure. Porch of the temple has domical chhatri. Drum of the temple is dedicated to Kangura pattern. Below drum
Bridge Tunnel	-	r uctures Public square Park or garden Graveyard Baolis, Well	of temple and is dedicated to Shiva. It has curvilinear superstructure. Porch of the temple has domical chhatri. Drum of the temple is dedicated to Kangura pattern. Below drum there is chajja. Temple has pillars
Bridge Tunnel	-	ructures Public square Park or garden Graveyard Baolis, Well Tank	of temple and is dedicated to Shiva. It has curvilinear superstructure. Porch of the temple has domical chhatri. Drum of the temple is dedicated to Kangura pattern. Below drum

4. Property Use ABANDONED / IN USE : In use Present Religious 2 Religious Past : 5. Age (Source) 18th Century A.D. PERIOD 2 YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History Temple 2 In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural It has curvilinear superstructure \checkmark Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Temple is oriented East-West and faces the West
•	RCHITECTURAL STYLEOrnamentationExteriorsInteriorsMovable CollectionsNy Other (specify)	:	Curvilinear superstructure, domical chhatri, Kangura pattern Shiv Linga
10	. Construction Technology		

Structural System	:	Nagar Style of temple
Building Techniques	:	Trabeate & Arcuate system
Material of Construction	:	Bricks & Stone

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration

Senous Detenoration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface, vegetation growth, Blackening of surface

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS