

Past

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/BUN-305 **SECTION I: IDENTIFICATION** 1. Name Present Mandir Shree Bandhidhar Nath jee Other Name (if any): 2. Location LONGITUDE 76° 19' E **LATITUDE** 25⁰ 53' N **Address** Nagadi Bazar, Bundi Village (village code) Post: Bundi District: Bundi State: Rajasthan **PIN**: 323001 Approach This Temple is situated at Bundi city. It is 1 km away from Bundi bus stand. It is well connected by bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: lt has domical structures superstructure with ribbed pattern Public square along with two canopied chhatris. Bridge Tunnel Park or garden Other engineering structure Graveyard

Baolis, Well Tank Cave

4. Property Use				
		ABANDONED / IN USE: In use		
Present Past	:	Religious Religious		
5. Age (Source)				
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : :	19 th Century A.D.		
6. Ownership / Level of Protection				
India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify)	:	SINGLE /MULTIPLE : Kasera Samaj Bundi		
Name Address Phone 7. Association	:			
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance		Temple		
Architectural Archaeological Historical Religious Any other (specify)	Do	omical superstructure		

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	tive Features
 Context Urban / Rural Setting Surroundings 			* Drawings (Attach extra sheet if necessary) Urban
	our our uning		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x F	Н) :	(m / am/fact / in ah)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01
•	Spatial Organization Orientation	:	The Temple is oriented at East-West & faces to the West
	Plan Allocation of Spaces	:	vvost
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :	Canopied chhatris
10.	Construction Technology	y	
44	Structural System Building Techniques Material of Construction	: :	Indo-Persian Arcuate system Brick and plaster
11.	Condition Assessment		
	In General	Good Good	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance	e	
In I	Brief (Attach extra sheet if	f neces	ssary):
80	ot denosition on the surface		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
IVAIVIE	IVAIIIL
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS