

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No.: RJ/CHR-074
1. Name	SECTION I : IDENTIFICATIO	DN
Present Past Other Name (if any): 2. Location	: Ram Chandra Bania	Ki Haveli
LONGITUDE 75° 41 [°] E	LATITUDE 29 ⁰ 0 [°] N	
Address	Ratan Nagar, Churu	
Approach 3. Property Type		e) District: Churu PIN: 331021 d at Ratan Nagar in Churu district. n Churu. It is well connected by
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar ✓ Others (specify) Haveli
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: This structure has chajja and brackets. It has pointed arch opening.

4. Property Use

: Residential : 19 th Century AD
: 19 th Century AD : :
: 19 th Century AD : :
: : : :
: : :
:
:
:
n
SINGLE /MULTIPLE :
:
: Haveli
•

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Haveli is oriented at East/West and faces the East.	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Ny Other (specify)	: : : : : : : : : : : : : : : : : : : :	Chajja with brackets	

10. Construction Technology

Structural System	:	Indo - Persian
Building Techniques	:	Arcuate
Material of Construction	:	Bricks & Stone

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Plaster peeling off, Blackening of surface.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS