

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No.: RJ/CHR-098
1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Seth Om Ka Haveli :	
LONGITUDE 75° 41' E	LATITUDE 29 ⁰ 0 ['] N	
Address	Churu city, Churu	
Approach		District: Churu PIN: 331403 It Churu city. It is 2 Km away It is well connected by regular
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures Temple	Other Structures Wall Gateway Pillar Others (specify) Haveli
Engineering structure Bridge Tunnel Other engineering structure	• •	Note: This Haveli has chajja and brackets. It has foliated arches.

4. Property Use

	ABANDONED / IN USE : In use
Present	:
Past	:
5. Age (Source)	
PERIOD	: 17 th Century AD
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	: Haveli
In Rituals	:
In Building Construction	:
Any other (specify)	:
 WITH PERSONS 	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
✓ Architectural	Foliated arches
Archaeological	
Historical	
Religious	

SECTION II: DESCRIPTION

9.	Physical Description and De	cora	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Haveli is oriented at North/South and faces the South.
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Chajja with brackets

10. Construction Technology

Structural System	:	Indo - Persian
Building Techniques	:	Arcuate
Material of Construction	:	Bricks & Stone

11. Condition Assessment

Good / Fair Good

Sign of Deterioration Serious Deterioration

Senous Detenoration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS