

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No.: RJ/CHR-108
1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Bala jee Maharaj Mandir : :	
LONGITUDE 75° 41' E	LATITUDE 29 ⁰ 0 [°] N	
Address	Churu city, Churu	
Approach		District: Churu PIN: 331403 at Churu city. It is 2 Km away It is well connected by regular
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures ✓ Temple Mosque	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	• •	lote: This temple has canopied hhatri and foliated arches.

4. Property Use ABANDONED / IN USE : In use Present Religious 2 Religious Past : 5. Age (Source) 17th Century AD PERIOD : YEARS : Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History Temple 2 In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Foliated arches \checkmark Archaeological Historical

Religious

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features					
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented at North/South and faces the South.		
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections ny Other (specify)	:	Canopied chhatri		

10. Construction Technology

Structural System	:	Indo - Persian
Building Techniques	:	Arcuate
Material of Construction	:	Bricks & Stone

11. Condition Assessment

Good / Fair Good

Sign of Deterioration Serious Deterioration

Senous Detenoration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS